



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

OPINION ON REPAIR COST FOR VEHICLE NO. SLV 4391L

Qty	Description of Parts	Condition	Recommended (\$)
<u>REPLACEMENT OF PARTS</u>			
1	WINDSCREEN	BROKEN	700.00
1	WINDSCREEN BOND KIT (NPA)	NOT NECESSARY	-
1	WINDSCREEN MOULDING	NECESSARY	50.00
1	R/R WDW FRAME MLDG	NECESSARY	30.00
1	GLASS SUNROOF CPL	BROKEN	10,300.00
1	R/ROOF MOULDING	DENTED	1,000.00
1	R/F ROOF MOULDING	CUT	75.00
1	HEADLINING	DEFORMED	4,800.00
			16,955.00
<u>SPECIAL NETT ITEMS</u>			
1	SUNDRY (SN)	NECESSARY	100.00
1	ERP BRACKET (SN)	NECESSARY	15.00
1	SEALANT (SN)	NECESSARY	25.00
			140.00
<u>LABOUR</u>			
CHECK WIRING.			50.00
171.0 WU X 42.00 SGD/H.			718.20
LABOUR COST 341.0 WU X 42.00 SGD/H.			1,432.20
MATERIAL COST.			570.59
			2,770.99
GRAND TOTAL			19,865.99

RECOMMENDED COST OF REPAIRS			19,865.99
------------------------------------	--	--	------------------

Report Ref No. CS3/CWF22001964/Cvy3e2-1

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.