

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 559K

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|--|-------------|----------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | FRONT BUMPER | BENT | 481.80 | 481.80 |
| 1 | FRONT BUMPER O/S BRACKET | BENT | 55.60 | 55.60 |
| 1 | FRONT PANEL | BENT | 1,019.30 | 1,019.30 |
| 1 | FRONT GRILLE | CRACKED | 561.60 | 561.60 |
| 1 | FRONT 'TOYOTA' EMBLEM | NECESSARY | 81.10 | 81.10 |
| 1 | FRONT 'DYNA' EMBLEM | NECESSARY | 65.20 | 65.20 |
| 1 | FRONT WIPER PANEL | BENT | 381.80 | 381.80 |
| 1 | FRONT O/S TOP GARNISH | CRACKED | 178.30 | 178.30 |
| 1 | FRONT TOP CENTRE GARNISH | SERVICEABLE | 294.10 | - |
| 1 | O/S HEALAMP | CRACKED | 673.30 | 673.30 |
| | LESS 25% DISCOUNT | | -948.03 | -874.50 |
| | | | 2,844.07 | 2,623.50 |
| | <u>LABOUR</u> | | | |
| | TO REMOVE & REFIT FRONT WINDSCREEN GLASS. | | 100.00 | 60.00 |
| | TO REMOVE & REFIT DASH BOARD & WIRING. | | 180.00 | 180.00 |
| | TO PANELBEAT & REPAIR FRONT INNER PANEL, CUT/WELD & FRONT PANEL,REPLACE THE ABOVE PARTS. | | 750.00 | 650.00 |
| | TO PUTTY & SPRAY PAINTING. | | 700.00 | 650.00 |
| | | | 1,730.00 | 1,540.00 |
| | GRAND TOTAL | | 4,574.07 | 4,163.50 |

| RECOMMENDED COST OF LUMP SUM REPAIRS | | 3,300.00 |
|--------------------------------------|--|----------|
| (TO ITS PRE-ACCIDENT CONDITION) | | |

Report Ref No. CS/LIP22011476/Kvy3m4

MARKET VALUE: \$25,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$1,426.00=NETT VALUE: \$23,574.00

KONG SENG CHEONG

Licensed Appraiser