

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. EM 7357Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
2	RUBBERRR QTR W/SHIELD (SN)	NECESSARY	15.60	15.60
1	CLIPQUARTER WINDSHIELD A (SN)	NECESSARY	2.92	2.92
1	CLIPQUARTER WINDSHIELD B (SN)	NECESSARY	2.92	2.92
1	CLIPQUARTER WINDSHIELD C (SN)	NECESSARY	1.95	1.95
1	WINDSCREEN SEALANT (SN)	NECESSARY	60.00	60.00
1	PANEL SET,R.RR.OUTSIDE (SN)	BADLY DENTED	440.17	440.17
1	STIFFENER COMP,R.RR (SN)	TO REPAIR SEE LABOUR	69.75	-
1	PANEL COMPRR. (SN)	BADLY DENTED	257.17	257.17
1	FACERR.BUMPER (SN)	DISTORTED	415.50	415.50
5	CLIP, BUMPER (SN)	NECESSARY	8.62	8.62
1	SPACERR.RR.BUMPER (SN)	BENT	8.62	8.62
4	ACT RR.SENSOR (SN)	SHORTED	320.00	320.00
1	GARNISHR.RR.BUMPER (SN)	TORN	11.40	11.40
1	TAILLIGHT ASSY,R. (SN)	CRACKED	193.80	193.80
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
1	COVERR.RR.FENDER (SN) (ADDITIONAL)	TWISTED	18.75	18.75
1	OUTLETRR AIR (SN) (ADDITIONAL)	TWISTED	20.25	20.25
			1,897.42	1,797.67
	<u>LABOUR</u>			
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER.		180.00	150.00
	REMOVE & RENEW REVERSE SENSORS - 4 PCS.		200.00	160.00
	BODY JOINT SEALANT.		200.00	200.00
	BODY UNDERSIDE COATING.		100.00	100.00
	APPLY BODY UNDERSIDE COATING.		250.00	150.00
	REMOVE & INSTALL RR.R QTR GLASS.		350.00	180.00
	REMOVE & INSTALL REAR COMPARTMENT LININGS.		450.00	350.00
	RESET VEHICLE SMART ENTRY SYSTEM.	NOT NECESSARY	450.00	-
	CUT & RENEW RR PANEL, GUTTER AND RR R FENDER. INCLUSIVE OF THE REPAIR OF STIFFENER COMP,R.RR.		5,500.00	4,875.00

Report Ref No. CS/SMR22011491/Uqy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)		2,800.00	2,080.00
			10,480.00	8,245.00
	GRAND TOTAL		12,377.42	10,042.67
	RECOMMENDED COST OF REPAIRS			10 042 67

Report Ref No. CS/SMR22011491/Uqy3e2

CHUA KANG SENG Licensed Appraiser