



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMP 2303A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BONNET	BENT	819.00	819.00
1	FRONT BONNET LOCK	TO REPAIR SEE LABOUR	121.70	-
2	FRONT BONNET HINGE @\$105.10	TO REPAIR SEE LABOUR	210.20	-
1	FRONT O/S FENDER	BUCKLED	475.30	475.30
1	FRONT O/S FENDER EMBLEM	NECESSARY	55.70	55.70
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	721.50	-
2	FRONT HEADLAMP @\$1458.70	N/S MTG CRACKED / O/S CRACKED	2,917.40	2,917.40
1	FRONT RADIATOR GRILLE	SERVICEABLE	1,014.20	-
1	FRONT RADIATOR GRILLE EMBLEM	SERVICEABLE	75.30	-
1	FRONT BUMPER	BUCKLED	900.40	900.40
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	385.70	-
1	FRONT BUMPER SPONGE	SERVICEABLE	107.20	-
1	FRONT BUMPER LOWER GRILLE	SERVICEABLE	146.30	-
2	FRONT BUMPER SIDE RETAINER @\$65.10	SERVICEABLE	139.20	-
1	WIPER TANK	SERVICEABLE	85.70	-
	LESS 20% DISCOUNT		-1,634.96	-1,033.56
			6,539.84	4,134.24
	<b><u>SPECIAL NETT ITEMS</u></b>			
20	FRONT BUMPER CLIP @\$2.00 (SN)	NECESSARY	40.00	40.00
			40.00	40.00
	<b><u>LABOUR</u></b>			
	REMOVE /RENEW THE ABOVE PARTS INCLUDING KNOCKING ,WELDING & CUTTING.INCLUSIVE OF THE REPAIR OF FRONT BONNET LOCK ,FRONT BONNET HINGE,FRONT SUPPORT PANEL AND FRONT BUMPER REINFORCEMENT .		1,200.00	500.00
	TO PUTTY AND SPRAY PAINT.		1,200.00	660.00
	CHECK & RECONNECT WIRING.		45.00	20.00

Report Ref No. CS/SMO22011495/Kwy3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RESPRAY ANTI-RUST PROOFING TREATMENT. REMOVE/REFIT AIR CON CONDENSER AND TO TOP UP GAS ELEMENT.	NOT NECESSARY	120.00 180.00 2,745.00	60.00 - 1,240.00
GRAND TOTAL			9,324.84	5,414.24
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,250.00

Report Ref No. CS/SMO22011495/Kwy3e2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.