



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCP 1311B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BOOTLID ASSY	DENTED	685.00	685.00
1	BOOT LOCK ASSY	DAMAGED	225.00	225.00
1	BOOT GARNISH PANEL	NOT NECESSARY	225.00	-
1	BOOT SEAL	NOT NECESSARY	215.00	-
1	LOCK STRIKER	NOT NECESSARY	85.00	-
1	END PANEL ASSY	TO REPAIR SEE LABOUR	875.00	-
1	END PANEL TOP GARNISH	DEFORMED	195.00	195.00
1	RR BUMPER ASSY	DEFORMED	685.00	685.00
1	RR REINFORCEMENT BEAM	BENT	365.00	365.00
2	RR BUMPER LH / RH REFLECTOR @\$95.00	NOT NECESSARY	190.00	-
1	RR LH TAILLAMP	NOT NECESSARY	375.00	-
2	RR BUMPER RETAINER LH / RH @\$85.00	NECESSARY	170.00	78.00
1	RR BUZZER MODULE	CRACKED	135.00	135.00
	LESS 20% DISCOUNT		-	-473.60
			4,425.00	1,894.40
<u>SPECIAL NETT ITEMS</u>				
1	"HONDA" EMBLEM (SN)	NECESSARY	85.00	45.00
1	"CIVIC" EMBLEM (SN)	NECESSARY	85.00	55.00
1	"VTEC" EMBLEM (SN)	NECESSARY	80.00	50.00
1	REAR SPOULER (BOOT) (SN)	NOT NECESSARY	375.00	-
1	SET BOOT CLIPS & FASTENERS (SN)	NECESSARY	80.00	30.00
2	REVERSE SENSOR (APPAREL) (SN)	DAMAGED	370.00	200.00
1	SET RR DIFUSSER (SN)	CRACKED	580.00	580.00
1	SET RR DIFUSSER 3RD BRAKE LIGHT (SN)	CUT	180.00	180.00
2	RR LH / RH REFLECTOR GARNISH @\$95.00 (SN)	NOT NECESSARY	190.00	-
1	SET RR BUMPER CLIPS & FASTENERS (SN)	NECESSARY	80.00	30.00
1	SET NUMBER PLATE (SN)	NOT NECESSARY	60.00	-
			2,165.00	1,170.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>LABOUR</u>			
	PANEL BEATING AFFECTED PANELS. INCLUSIVE OF THE REPAIR OF END PANEL ASSY.		700.00	600.00
	SPRAY PAINTING AFFECTED PANELS.		800.00	600.00
	CHECK WIRING.		120.00	30.00
	PAINT PROTECTION COATING.		880.00	300.00
			2,500.00	1,530.00
	GRAND TOTAL		9,090.00	4,594.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				3,650.00

Report Ref No. CS/INC22011496/Any3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.