

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22011499/AVP3Q2**Date:** 28/11/2022REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00005342202
Claimant Vehicle No :	SNH2550H	Insured Vehicle No :	SJV663C
Date of Loss:	15/11/2022	Nature of Claim:	TP
		Claim No:	SNM22D208205/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNH2550H	Engine No:	M15AY463411
Make & Model:	TOYOTA YARIS, 1.3 (A)	Chassis No:	JTDKBAB3201001838
Reg. Date:	11/10/2022 (Man. Year: 2022)	Odometer:	6568 km
Colour:	White		
Engine Capacity:	1490 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/65 R16	Rear Tyre Size:	205/65 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,898.35	4,721.36	1,176.99	19.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,400.00	1,930.00	1,470.00	43.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,298.35	6,651.36	2,646.99	28.47
Approved Total (Overridden) (\$\$)		5,300.00		
(\$\$)	9,298.35	5,300.00	3,998.35	43.00
+ GST 7.00/7.00% (\$\$)	650.88	371.00	279.88	43.00
Nett Amount (\$\$)	9,949.23	5,671.00	4,278.23	43.00

INSPECTION

Date of Assignment:	16/11/2022	
Date Inspected:	16/11/2022 Inspected At:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB Singapore 417921
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Nov 2022)
Parts:	144	TOYOTA YARIS 1.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNH2550H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (LOWER)	Deformed	525.50 FL	*525.50 FL
2	1		*REAR BUMPER (TOP)	Deformed	417.10 FL	*417.10 FL
3	1		*REAR BUMPER LH END SEAL COVER	Deformed	98.20 FL	*98.20 FL
4	1		*REAR BUMPER LH REFLECTOR	Cracked	59.00 FL	*59.00 FL
5	1		*REAR BUMPER LH REVERSE SENSOR	Damaged	364.20 FL	*250.00 FL
6	1		*REAR BUMPER SIDE RETAINER L/R	N/S Cracked	200.80 FL	*100.40 FL
7	1		*REAR END PANEL	Repair	696.30 FL	*- FL
8	1		*REAR END PANEL INNER TOP GARNISH	Not Necessary	218.00 FL	*- FL
9	1		*REAR LH FENDER	Buckled	1,217.90 FL	*1,217.90 FL
10	1		*REAR LH FENDER ARCH GARNISH	Distorted	185.90 FL	*185.90 FL
11	1		*REAR LH FENDER INNER AIR VENT	Deformed	161.25 FL	*161.25 FL
12	1		*REAR LH FENDER INNER SHIELD	Deformed	191.20 FL	*191.20 FL
13	1		*REAR LH FENDER INNER TRIM GARNISH	Deformed	627.00 FL	*627.00 FL
14	1		*REAR LH PANEL SENSOR	Cracked	1,603.00 FL	*1,603.00 FL
15	1		*REAR LH PANEL SENSOR GARNISH BRACKET	Cracked	67.10 FL	*67.10 FL
16	1		*REAR LH TAILLAMP	Cracked	492.50 FL	*492.50 FL
17	1		*REAR LH TAILLAMP LOWER BRACKET	Cracked	59.10 FL	*59.10 FL
18	1		*REAR TAILGATE CROSS EMBLEM	Not Necessary	42.95 FL	*- FL
19	1		*REAR TAILGATE HYBRID EMBLEM	Not Necessary	47.80 FL	*- FL
20	1		*REAR TAILGATE YARIS EMBLEM	Not Necessary	43.00 FL	*- FL
21	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
22	1		*SET REAR BUMPER LH END SEAL COVER CLIPS	Necessary	30.00 FS	*10.00 FS
23	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
24	1		*REAR END PANEL SELANAT	Not Necessary	80.00 FS	*- FS
25	1		*SET REAR LH FENDER ARCH GARNISH CLIPS	Necessary	30.00 FS	*20.00 FS
26	1		*SET REAR LH FENDER INNER SHIELD CLIPS	Necessary	30.00 FS	*20.00 FS
27	1		*SET REAR LH FENDER INNER TRIM GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
28	1		*REAR LH FENDER SEALANT	Necessary	80.00 FS	*60.00 FS
29	1		*SET REAR LH TAILLAMP CLIPS	Necessary	30.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,727.80	6,235.15
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,829.45	1,513.79
Total Parts (\$\$)	5,898.35	4,721.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RESET SYSTEM AFTER REPAIR WORKS	New	250.00	180.00
2	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	60.00	60.00
3	TO REMOVE ,REINSTALL PETROL TANK (TO FR)	New	100.00	80.00
4	TO REMOVE ,REINSTALL ROOF TOP TRIM UPHOLSTERY ,CUSHION SEAT ,TRIM GARNISH ,TRIM LINER CARPET (TO FR)	New	140.00	60.00
5	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,300.00	600.00
6	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,500.00	900.00
7	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	50.00	50.00
Gross Labour Cost (\$\$)			3,400.00	1,930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >