

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22011513/ANP3Q2**Date:** 21/12/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00099752202		
Claimant Vehicle No :	GBM311K	Insured Vehicle No :	GBG6132C		
Date of Loss:	15/11/2022	Nature of Claim:	TP	Claim No:	SNM22D208208/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBM311K	Engine No:	HIDDEN
Make & Model:	SOKON EC35, (A)	Chassis No:	LVPRPB4B2NC893608
Reg. Date:	30/09/2022 (Man. Year: 2022)	Odometer:	2129 km
Colour:	Silver		
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185 R14C	Rear Tyre Size:	185 R14C
Front Left Side:	Matrex 6 mm	Rear Left Side:	Matrex 6 mm
Front Right Side:	Matrex 6 mm	Rear Right Side:	Matrex 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,721.30	7,062.20	5,659.10	44.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,530.00	2,560.00	970.00	27.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,251.30	9,622.20	6,629.10	40.79
Approved Total (Overridden) (S\$)		7,600.00		
(S\$)	16,251.30	7,600.00	8,651.30	53.23
+ GST 7.00/7.00% (S\$)	1,137.59	532.00	605.59	53.23
Nett Amount (S\$)	17,388.89	8,132.00	9,256.89	53.23

INSPECTION

Date of Assignment:	15/12/2022		
Date Inspected:	16/11/2022	Inspected At:	2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921 Repairer:An-51 Automotive (HQ)
Estimated Period of Repair:	9.0 days		

Adjuster: ADRIAN LING**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 21 Dec 2022)	
Parts:	N/A	SOKON EC35 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBM311K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	782.00 F	*782.00 FL
2	2		*REAR BUMPER REFLECTOR L/R	Cracked	282.00 F	*282.00 FL
3	2		*REAR BUMPER SIDE RETAINER L/R	Cracked	250.00 F	*250.00 FL
4	1		*REAR END PANEL (INNER)	Dented	987.00 F	*545.00 FL
5	1		*REAR END PANEL (OUTER)	Dented	699.00 F	*699.00 FL
6	1		*REAR LH FENDER	Buckled	1,835.00 F	*1,200.00 FL
7	1		*REAR LH TAILLAMP INNER PANEL	Repair	489.10 F	*- FL
8	1		*REAR SPARE TYRE CARRIAGE	Bent	498.20 F	*325.00 FL
9	1		*REAR SPARE TYRE CARRIAGE SCREW WITH BRACKET	Bent	98.00 F	*98.00 FL
10	1		*REAR TAILGATE	Dented	1,928.00 F	*1,501.00 FL
11	1		*REAR TAILGATE LOGO EMBLEM	Necessary	73.00 F	*73.00 FL
12	1		*REAR TAILGATE CENTER LOCK CONTROL ASSY	Not Necessary	569.00 F	*- FL
13	2		*REAR TAILGATE HINGES L/R	Not Necessary	196.00 F	*- FL
14	1		*REAR TAILGATE INNER TRIM BOARD	Not Necessary	400.00 F	*- FL
15	1		*REAR TAILGATE LOCK STRIKER	Not Necessary	79.00 F	*- FL
16	1		*REAR TAILGATE MECHANISM LOCK	Damaged	178.00 F	*178.00 FL
17	2		*REAR TAILGATE NUMBER PLATE LAMP L/R	Not Necessary	210.00 F	*- FL
18	1		*REAR TAILGATE OUTER HANDLE	Not Necessary	325.00 F	*- FL
19	1		*REAR TAILGATE WEATHERSTRIP	Cut	305.00 F	*305.00 FL
20	2		*REAR TAILLAMP L/R	Cracked	938.00 F	*770.00 FL
21	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
22	1		*SET REAR BUMPER REVERSE SENSOR (3 EYES)	Damaged	320.00 FS	*250.00 FS
23	1		*REAR LH FENDER 3D STICKER	Necessary	800.00 FS	*350.00 FS
24	1		*REAR TAILGATE 70KM STICKER	Necessary	25.00 FS	*15.00 FS
25	1		*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
26	1		*REAR TAILGATE NUMBER PLATE	Not Necessary	25.00 FS	*- FS
27	1		*REAR TAILGATE NUMBER PLATE HOLDER	Not Necessary	50.00 FS	*- FS
28	1		*SET REAR TAILGATE OUTER HANDLE CLIPS	Not Necessary	40.00 FS	*- FS
29	1		*REAR TAILGATE WINDSCREEN SEAL	Necessary	80.00 FS	*40.00 FS
30	1		*REAR TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
31	2		*SET REAR TAILLAMP CLIPS L/R	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	12,721.30	7,763.00
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	700.80
Total Parts (\$)	12,721.30	7,062.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING AND REWIRE FOR PAKRING SENSOR	New	80.00	50.00
2	TO REMOVE ,REINSTALL TAILGATE WINDSCREEN	New	150.00	120.00
3	TO REMOVE ,REINSTALL ROOF TOP TRIM UPHOLSTERY ,CUSHION SEAT ,TRIM GARNISH ,TRIM LINER CARPET (TO FR)	New	100.00	50.00
4	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,200.00	1,000.00
5	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,800.00	1,200.00
6	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	60.00
7	TO REMOVE ,REINSTALL TAILGATE MECHANISM AND CHECK FOR FUNCTION	New	80.00	80.00
Gross Labour Cost (\$\$)			3,530.00	2,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >