



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBK 8711Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR FENDER LH (CONSISTENT)	TO REPAIR SEE LABOUR	978.20	-
1	REAR SLIDING DOOR LH (CONSISTENT)	DENTED / WARPED	1,541.20	1,541.20
1	CENTER PANEL LH (CONSISTENT)	BENT	923.40	861.10
	LESS 25% DISCOUNT		-860.70	-600.58
			2,582.10	1,801.72
	<u>SPECIAL NETT ITEMS</u>			
1	'COMPANY' STICKER (SN) (CONSISTENT)	NECESSARY	350.00	200.00
			350.00	200.00
	<u>LABOUR</u>			
	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT .		1,000.00	600.00
	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-ALIGN BODY STRUCTURE BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT .INCLUSIVE OF THE REPAIR OF REAR FENDER LH.		1,000.00	600.00
			2,000.00	1,200.00
	GRAND TOTAL		4,932.10	3,201.72
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,550.00

Report Ref No. CC4/ASM22011522/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.