

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YQ 2107C**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT WINDSCREEN	BROKEN	1,697.40	1,697.40
1	FRONT WINDSCREEN RUBBER	CUT / TWISTED	399.40	399.40
1	FRONT WINDSCREEN WIPER ARM N/S	BENT	173.40	173.40
1	FRONT WINDSCREEN WIPER ARM O/S	BENT	151.00	151.00
2	FRONT WINDSCREEN WIPER BLADES @\$48.60	BENT	97.20	97.20
1	FRONT WIPER PANEL	TO REPAIR SEE LABOUR	433.20	-
1	FRONT SIDE MIRROR BRACKET ASSY N/S	BENT	555.00	555.00
1	DASHBOARD	CUT	1,090.40	1,090.40
1	FRONT ERP BRACKET	NECESSARY	25.00	25.00
	LESS 10% DISCOUNT		-462.20	-418.88
			4,159.80	3,769.92
	<b><u>LABOUR</u></b>			
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REPLACED FRONT WINDSCREEN.		120.00	100.00
	TO DISMANTLE & REPLACED DASHBOARD.		280.00	250.00
	TO SPRAY RUST PROOFING.	NOT NECESSARY	50.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF FRONT WIPER PANEL.		480.00	420.00
	TO PUTTY & SPRAY PAINTING.		450.00	200.00
			1,430.00	990.00
<b>GRAND TOTAL</b>			<b>5,589.80</b>	<b>4,759.92</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,800.00</b>

Report Ref No. CS/TP22011527/Uqy3m4

**CHUA KANG SENG**

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.