

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22011528/KYA3Q2**Date:** 12/05/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800155281
Claimant Vehicle No :	SHC5175K	Insured Vehicle No :	SMG7034R
Date of Loss:	09/11/2022	Nature of Claim:	TP
		Claim No:	4138715657SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC5175K		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2H19524
Reg. Date:	13/11/2020 (Man. Year: 2020)	Chassis No:	JTDKB3FU603092728
Colour:	Metallic Pearl White/Red	Odometer:	200146 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Wanli 7 mm	Rear Left Side:	LANVIGATOR 6 mm
Front Right Side:	Wanli 7 mm	Rear Right Side:	LANVIGATOR 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,275.90	954.60	2,321.30	70.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,300.00	470.00	4,830.00	91.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	8,575.90	1,424.60	7,151.30	83.39
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	14/11/2022		
Date Inspected:	14/11/2022	Inspected At:	Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.0 days		

Adjuster: KENNETH KONG**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,REAR BUMPER	Bent	485.60 FL	*485.60 FL
2	1		*REINFORCEMENT SUB-ASSY ,REAR BUMPER	Bent	332.70 FL	*332.70 FL
3	1		*GUARD ,REAR BUMPER CENTER	Dented / Cut	374.50 FL	*374.50 FL
4	1		*SEAL,REAR BUMPER SIDE ,LH	Serviceable	118.30 FL	*- FL
5	1		*SEAL,REAR BUMPER SIDE ,RH	Serviceable	118.30 FL	*- FL
6	1		*RETANER ,REAR BUMPER SIDE ,RH	Serviceable	132.60 FL	*- FL
7	1		*RETANER ,REAR BUMPER SIDE ,LH	Serviceable	132.60 FL	*- FL
8	1		*COVER ,REAR BUMPER ,LOWER	Serviceable	22.00 FL	*- FL
9	1		*COVER ,DECK TRIM REAR	Serviceable	126.70 FL	*- FL
10	1		*COVER ,FLOOR UNDER NO.2 (RH)	Serviceable	241.90 FL	*- FL
11	1		*COVER ,FLOOR UNDER NO.1 (LH)	Serviceable	175.10 FL	*- FL
12	1		*COVER ,REAR FLOOR (CTR)	Serviceable	229.90 FL	*- FL
13	1		*PANEL SUB-ASSY ,BODY LOWER BACK	Repair	651.00 FL	*- FL
14	1		*REAR BUMPER SIDE CLIP	Not Necessary	60.00 FS	*- FS
15	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
16	1		*SET REAR BUMPER CLIP	Necessary	85.00 FS	*60.00 FS
17	1		*REAR BUMPER RETAINER CLIP	Not Necessary	75.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					4,061.20	1,252.80
- List Item Discount on L Items 25.00/25.00% (\$\$)					785.30	298.20
Total Parts (\$\$)					3,275.90	954.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	0.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	1,800.00	200.00
4	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS TO FACILITATE BODYWORK REPAIR	New	380.00	0.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,600.00	220.00
6	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
7	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
10	TO REMOVE AND REFIT OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
Gross Labour Cost (S\$)			5,300.00	470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >