

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/AIG22011532/KYA3Q2**Date:** 12/05/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210155647
<b>Claimant Vehicle No :</b>	SHF711E	<b>Insured Vehicle No :</b>	YQ5432T
Date of Loss:	04/11/2022	Nature of Claim:	TP
		Claim No:	9658903589SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SHF711E</b>		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2H13735
Reg. Date:	30/11/2021 (Man. Year: 2020)	Chassis No:	JTDKB3FU403092565
Colour:	Metallic Pearl White/Red	Odometer:	78753 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Wanli 8 mm	Rear Left Side:	Wanli 8 mm
Front Right Side:	Wanli 8 mm	Rear Right Side:	Wanli 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,068.65	280.87	5,787.78	95.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,300.00	420.00	4,880.00	92.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>11,368.65</b>	<b>700.87</b>	<b>10,667.78</b>	<b>93.84</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

**INSPECTION**

Date of Assignment:	14/11/2022		
Date Inspected:	14/11/2022	Inspected At:	Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.0 days		

**Adjuster:** KENNETH KONG**Manager:** Ezlyna

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER, REAR BUMPER	Serviceable	485.60 FL	*- FL
2	1		*REINFORCEMENT SUB-ASSY, REAR BUMPER	Repair	332.70 FL	*- FL
3	1		*GUARD, REAR BUMPER, CENTER	Dented	374.50 FL	*374.50 FL
4	1		*SEAL, REAR BUMPER SIDE, LH	Serviceable	118.30 FL	*- FL
5	1		*SEAL, REAR BUMPER SIDE, RH	Serviceable	118.30 FL	*- FL
6	1		*RETAINER, REAR BUMPER SIDE, RH	Serviceable	132.60 FL	*- FL
7	1		*RETAINER, REAR BUMPER SIDE, LH	Serviceable	132.60 FL	*- FL
8	1		*COVER, REAR BUMPER, LOWER	Serviceable	22.00 FL	*- FL
9	1		*COVER, DECK TRIM, REAR	Serviceable	126.70 FL	*- FL
10	1		*COVER, FLOOR UNDER, NO.2 (RH)	Serviceable	241.90 FL	*- FL
11	1		*COVER, FLOOR UNDER, NO.1 (LH)	Serviceable	175.10 FL	*- FL
12	1		*COVER, REAR FLOOR (CTR)	Serviceable	229.90 FL	*- FL
13	1		*PANEL SUB-ASSY, BODY LOWER BACK	Repair	651.00 FL	*- FL
14	1		*PANEL SUB-ASSY, BACK DOOR	Repair	1,147.80 FL	*- FL
15	1		*PLATE, LUGAGGE COMPARTMENT DOOR NAME, NO.2	Not Necessary	54.60 FL	*- FL
16	1		*PLATE, BACK DOOR NAME, NO.1	Not Necessary	54.60 FL	*- FL
17	1		*ORNAMENT SUB-ASSY, BACK DOOR	Not Necessary	47.90 FL	*- FL
18	1		*GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	Serviceable	913.60 FL	*- FL
19	1		*BOARD ASSY, BACK DOOR TRIM	Serviceable	259.20 FL	*- FL
20	1		*WEATHERSTRIP, BACK DOOR	Serviceable	372.30 FL	*- FL
21	1		*STAY ASSY, BACK DOOR, LH	Serviceable	242.50 FL	*- FL
22	1		*STAY ASSY, BACK DOOR, RH	Serviceable	242.50 FL	*- FL
23	1		*HINGE ASSY, BACK DOOR, LH	Repair	61.00 FL	*- FL
24	1		*HINGE ASSY, BACK DOOR, RH	Repair	61.00 FL	*- FL
25	1		*REAR BUMPER SIDE CLIP	Not Necessary	60.00 FS	*- FS
26	1		*BOOT STICKER TRANSCAB	Not Necessary	100.00 FS	*- FS
27	1		*BOOT STICKER TEL NO	Not Necessary	100.00 FS	*- FS
28	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
29	1		*SET REAR BUMPER CLIP	Not Necessary	85.00 FS	*- FS
30	1		*REAR BUMPER RETAINER CLIP	Not Necessary	75.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,718.20	374.50
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,649.55	93.63
Total Parts (\$\$)	6,068.65	280.87

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	0.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR	New	380.00	0.00
3	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	1,800.00	200.00
4	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT TO FACILITATE BODYWORK REPAIR	New	380.00	0.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,600.00	220.00
6	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
7	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	0.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
10	TO REMOVE AND REFIT OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,300.00</b>	<b>420.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >