5/12/23, 12:19 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG22011534/KYA3Q2

12/05/2023 Date:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100346403 **Claimant Vehicle**

SHD267G Insured Vehicle No: EU8888H No:

Date of Loss: 02/11/2022 Nature of Claim: TP Claim No: 4558323388SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD267G

RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR Engine No: Make & Model: M9R8839C002921 (A)

VF1ABL15AUC282311 Reg. Date: 20/11/2015 (Man. Year: 2015) Chassis No:

Colour: Metallic White/Red Odometer: 866733 km

Engine Capacity: 1995 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Yes Engine Modification: Pre-accident Condition: Handbrake (Serviceable): No

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16 Rear Left Side: Front Left Side: Firenza 9 mm Sailun 7 mm Front Right Side: Firenza 9 mm Rear Right Side: Sailun 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,571.52	60.00	9,511.52	99.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,240.00	740.00	9,500.00	92.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	19,811.52	800.00	19,011.52	95.96

0.00 Global Sum Settlement (S\$)

INSPECTION

Date of Assignment: 14/11/2022

Trans-cab Auto Services Pte Ltd Date Inspected: 14/11/2022 Inspected At:

No 2 Ang Mo Kio Street 63

Singapore 569111

Estimated Period of Repair: 2.0 days

Adjuster: **KENNETH KONG** Manager: Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

t No. Particulars	Condition	Repairer's	Amount
*DOOR PANEL REAR RH	Repair	2,844.66 FL	*- FL
*DOOR WEATHERSTRIP REAR RH	Serviceable	311.60 FL	*- FL
*DOOR HANDLE MODULE REAR RH	Serviceable	133.40 FL	*- FL
*DOOR HANDLE OUTER REAR RH	Serviceable	42.10 FL	*- FL
*DOOR REGULATOR REAR RH	Serviceable	450.60 FL	*- FL
*DOOR REGULATOR MOTOR REAR RH	Serviceable	758.10 FL	*- FL
*DOOR REGULATOR UPPER REAR RH	Repair	241.60 FL	*- FL
*DOOR REGULATOR LOWER REAR RH	Repair	169.90 FL	*- FL
*FENDER PANEL REAR RH	Repair	1,933.20 FL	*- FL
*WHEELARCH REAR RH	Serviceable	275.40 FL	*- FL
*BUMPER COVER REAR	Serviceable	561.70 FL	*- FL
*ROCKER PANEL OUTER RH	Repair	1,184.99 FL	*- FL
*FENDER LINER CLIP	Not Necessary	60.00 FS	*- FS
*REAR BUMPER CLIP	Not Necessary	60.00 FS	*- FS
*RIM	Serviceable	350.00 FS	*- FS
*TYRE	Serviceable	300.00 FS	*- FS
*DOOR TRIM CLIP	Not Necessary	70.00 FS	*- FS
*DOOR SEAL CLIP	Not Necessary	65.00 FS	*- FS
*DOOR MOULDING CLIP	Not Necessary	70.00 FS	*- FS
*DOOR STICKER 65553333	Necessary	100.00 FS	*60.00 FS
*WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS
*WINDSCREEN MOULDING	Not Necessary	200.00 FS	*- FS
*WINDSCREEN INNER SPONGE SEAL	Not Necessary	130.00 FS	*- FS
S=SpcNett. L=ListItemDisc.	_		
	Sub Total (S\$)	10,462.25	60.00
- List Item Discount or	890.73	0.00	
	Total Parts (S\$)	9,571.52	60.00
		- List Item Discount on L Items 10.00/10.00% (S\$) Total Parts (S\$) Report was unsubmitted during this print-out.	Total Parts (S\$) 9,571.52

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	300.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New T	6,000.00	440.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
5	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
7	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
8	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
9	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
	Gross Labor	ur Cost (S\$)	10,240.00	740.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >