



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PA 9085B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	N/S SIDE VIEW MIRROR ASSEMBLY }	CRACKED	4,788.90	3,520.00
1	N/S SIDE VIEW MIRROR ARM }		1,280.00	-
1	N/S SIDE VIEW MIRROR COVER }		890.00	-
1	N/S SIDE VIEW MIRROR - BIG }		580.00	-
1	N/S SIDE VIEW MIRROR - SMALL }		467.00	-
1	N/S SIDE VIEW MIRROR MOTOR }		786.00	-
1	N/S SIDE VIEW SMALL MIRROR COVER }		468.00	-
1	N/S SIDE VIEW SMALL MIRROR }		318.00	-
1	FRONT PANEL L/H	NOT NECESSARY	1,800.00	-
1	FRONT CAMERA L/H	NOT NECESSARY	589.00	-
1	SIGNAL COVER L/H	NOT NECESSARY	88.90	-
1	FRONT HEADLIGHT L/H	NOT NECESSARY	3,988.50	-
1	FRONT HEADLIGHT R/H	NOT NECESSARY	3,988.50	-
1	FRONT BUMPER	NOT NECESSARY	1,890.00	-
1	REAR BUMPER	NOT NECESSARY	1,990.00	-
	LESS 10% DISCOUNT		-2,391.28	-
	LESS 15% DISCOUNT		-	-528.00
			21,521.52	2,992.00
	<b><u>LABOUR</u></b>			
	TO REMOVE AND REPLACED DAMAGED PARTS.		950.00	280.00
	TO RESPRAY AFFECTED PANEL.		1,900.00	200.00
	TO CHECK ON ELECTRICAL WIRING FOR CAMERA, HEADLIGHT AND O/S MIRROR.		980.00	50.00
			3,830.00	530.00
	<b>GRAND TOTAL</b>		<b>25,351.52</b>	<b>3,522.00</b>



<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,800.00</b>
---	--	--	-----------------

Report Ref No. CS/LPC22011535/Uqy3m4

**CHUA KANG SENG**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**