

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | | |
|---|--|---|-----------------|------|-----------------------|--|
| | LONPAC INSURAN | NCE BHD | Re | ef: | CS/LPC22011535/Uqy3m4 | |
| | 300 BEACH ROAD #17-04/07 THE CO | NCOURSESINGAPORE 199555 | Da | ate: | 28/11/2022 | |
| | | | Co | ode: | LPC2 | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | | |
| | Insured Veh. | YQ 2070Z | Veh. Inspected | | PA 9085B | |
| | Policy No. | | Coverage (\$) | | 0.00 | |
| | Claim No. | 22/22/22/VC05/026306 | Excess (\$) | | 0.00 | |
| | Assign From | GERALD POH | Assign Date | | 17/11/2022 | |
| 2. Vehicle Particulars & Condition | | | | | | |
| | Make & Model | ISUZU LT134P | c.c | | 7790 | |
| | Engine No. | HIDDEN | Year of Reg. | | 2009 | |
| | Chassis No. | JALLT134P87000171 | Colour | | WHITE / BLUE | |
| | Odometer | 479612 KM | Steering | | IN ORDER | |
| | Brakes | IN ORDER | Modification | | NIL | |
| | General | GOOD | | | | |
| 3. Conditions of Tyres | | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 295/80 R22.5 | DUNLOP | | 6 mm | |
| | L/H Front Tyre | 295/80 R22.5 | DUNLOP | | 6 mm | |
| | R/H Rear Tyre | 295/80 R22.5 (D/D) | DUNLOP | | 6/6 mm | |
| | L/H Rear Tyre | 295/80 R22.5 (D/D) | DUNLOP | | 6/6 mm | |
| 4. | . Description of Damages | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. | | | | | |
| | DAMAGES SEE DETAILS. | | | | | |
| 5. | General Information | | | | | |
| | Accident Date | 18/09/2022 | Inspection Date | | 15/11/2022 | |
| | Survey held at | urvey held at EURO SUCCESS SERVICES PTE LTD 1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY @ KAKI BUKIT SINGAPORE 417883 | | | | |
| | | | | | | |
| 5a. | Remarks | | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |
| 5b. | Estimate Days of Repair | | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days | | | | | |
| | | | | | | |