

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22011548/AGY3E2
Date: 13/02/2023REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001959447
Claimant Vehicle No :	SLE499B	Insured Vehicle No :	SLF8287M
Date of Loss:	15/11/2022	Nature of Claim:	TP
		Claim No:	291122

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE499B	Engine No:	L15B4036598
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Chassis No:	RU11116593
Reg. Date:	05/07/2016 (Man. Year: 2016)	Odometer:	121322 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R18	Rear Tyre Size:	225/50 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,730.56	2,530.56	2,200.00	46.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,230.00	1,390.00	1,840.00	56.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,960.56	3,920.56	4,040.00	50.75
Approved Total (Overridden) (S\$)		3,100.00		
	(S\$)	7,960.56	3,100.00	4,860.56
+ GST 8.00/8.00% (S\$)	636.84	248.00	388.84	61.06
Nett Amount (S\$)	8,597.40	3,348.00	5,249.40	61.06

INSPECTION

Date of Assignment:	17/11/2022		
Date Inspected:	05/12/2022	Inspected At:	Modern Automotive Pte Ltd (HQ) Blk 3023A Ubi Road 1, #01-61 & #01-58 Singapore 408717
Estimated Period of Repair:	4.0 days		

Adjuster: XING GUO QIANG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 10 Feb 2023)
Parts: M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLE499B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	765.40 FL	*765.40 FL
2	2		*REAR BUMPER SIDE HOLDER - LH & RH	Necessary	49.00 FL	*49.00 FL
3	2		*REAR BUMPER REFLECTOR - LH & RH	Not Necessary	282.20 FL	*- FL
4	1		*REAR END PANEL	Not Necessary	585.40 FL	*- FL
5	1		*REAR END PANEL TOP GARNISH	Not Necessary	98.40 FL	*- FL
6	1		*REAR END PANEL BUZZER	Not Necessary	85.20 FL	*- FL
7	1		*REAR END PANEL ANTENNA SENSOR	Not Necessary	101.40 FL	*- FL
8	1		*TAILGATE	Dented	1,100.00 FL	*1,100.00 FL
9	1		*TAILGATE LOCK	Damaged	182.50 FL	*182.50 FL
10	1		*TAILGATE WEATHERSTRIPE	Not Necessary	194.90 FL	*- FL
11	1		*TAILGATE GLASS MOULDING	Necessary	120.40 FL	*120.40 FL
12	1		*VEZEL EMBLEM	Necessary	45.90 FL	*45.90 FL
13	1		*SPARE TYRE PANEL UNDERCOVER	Not Necessary	285.10 FL	*- FL
14	1		*REAR EXHAUST PIPE	Repair	598.60 FL	*- FL
15	1		*REAR EXHAUST PIPE MOUNTING	Not Necessary	35.40 FL	*- FL
16	1		*REAR EXHAUST PIPE GASKET	Not Necessary	33.40 FL	*- FL
17	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
18	1		*REAR BUMPER OUTER CHROME MOULDING	Bent	250.00 FS	*180.00 FS
19	1		*REAR BUMPER TOP GARNISH	Bent	350.00 FS	*250.00 FS
20	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
21	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	20.00 FS	*- FS
22	1		*REAR END PANEL SEALANT	Not Necessary	60.00 FS	*- FS
23	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
24	1		*SET SPARE TYRE PANEL UNDERCOVER CLIPS	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,643.20	2,983.20
- List Item Discount on L Items 20.00/20.00% (\$)	912.64	452.64
Total Parts (\$)	4,730.56	2,530.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCKING & PULL OUT REAR PORTION & RENEW ABOVE PARTS	New	1,200.00	500.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	1,000.00	400.00
3	TO CHECK WIRING	New	100.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE REAR CAMERA	New	100.00	50.00
6	TO REMOVE REAR VIDEO RECORDER	New	100.00	50.00
7	TO REMOVE UPHOLSTERY	New	150.00	30.00
8	TO TRANSFER TAILGATE FITTINGS	New	150.00	80.00
9	TO REMOVE TAILGATE GLASS	New	180.00	120.00
10	TO REMOVE REAR EXHAUST PIPE	New	150.00	80.00
			Gross Labour Cost (\$)	3,230.00
				1,390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >