



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YN 8693C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR SAFETY BAR (SN)	TO REPAIR SEE LABOUR	2,500.00	-
1	WOODEN PLANK (SN)	CRACKED	1,800.00	600.00
1	REAR CABIN DOOR RH (SN)	DENTED	1,200.00	1,000.00
1	REAR CABIN DOOR LH (SN)	DENTED	1,200.00	1,000.00
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
1	REAR CABIN DOOR HINGE RH (SN)	NOT NECESSARY	250.00	-
1	REAR CABIN DOOR HINGE LH (SN)	NOT NECESSARY	250.00	-
1	ADVERTISEMENT STICKER (SN) (ADDITIONAL)	NECESSARY	600.00	600.00
			7,850.00	3,200.00
	<u>LABOUR</u>			
	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS. INCLUSIVE OF THE REPAIR OF REAR SAFETY BAR.		1,400.00	500.00
	TO SPRAY PAINT ON AFFECTED AREAS.		600.00	200.00
			2,000.00	700.00
	GRAND TOTAL		9,850.00	3,900.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,100.00

Report Ref No. CS/FCI22011560/Uwy3e2

MARKET VALUE: \$40,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$5,223.00=NETT VALUE: \$34,777.00

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.