



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI22011560/Uwy3e2 Date: 30/12/2022 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YM 3264X	Veh. Inspected	YN 8693C
Policy No.	D-22099586MFCV/13	Coverage (\$)	0.00
Claim No.	D22003626MFCV	Excess (\$)	0.00
Assign From	CAROLINE CABRERA	Assign Date	17/11/2022
2. Vehicle Particulars & Condition			
Make & Model	ISUZU NNR85UH4A (M)	c.c	2999
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JAANNR85HE7100443	Colour	WHITE
Odometer	218897 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/85 R16	WEST LAKE	6 mm
L/H Front Tyre	195/85 R16	WEST LAKE	6 mm
R/H Rear Tyre	195 R15	FALKEN	6/6 mm
L/H Rear Tyre	195 R15	FALKEN	6/6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	16/11/2022	Inspection Date	05/12/2022
Survey held at	ABWIN SERVICE PTE LTD 17 KAKI BUKIT ROAD 4 #01-60 BARTLEY BIZ CENTRE SINGAPORE 417809		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	