

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22011564/UWP3Q2**Date:** 08/12/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00138842203

**Claimant Vehicle No :** SNG9403J **Insured Vehicle No :** SLD6495C

Date of Loss: 12/11/2022 Nature of Claim: TP Claim No: SNM22D208179/C02/TANKL

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SNG9403J**

Make & Model: KIA CERATO, 1.6 (A) Engine No: G4FGMH717545

Reg. Date: 16/09/2022 (Man. Year: 2021) Chassis No: KNAF5416MN5131336

Colour: Red Odometer: 3394 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES**

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17

Front Left Side: Kumho 8 mm Rear Left Side: Kumho 8 mm

Front Right Side: Kumho 8 mm Rear Right Side: Kumho 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,955.00	3,122.00	1,833.00	36.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,790.00	4,210.00	4,580.00	52.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>13,745.00</b>	<b>7,332.00</b>	<b>6,413.00</b>	<b>46.66</b>
<b>+ GST 7.00/7.00% (S\$)</b>	962.15	513.24	448.91	46.66
<b>Nett Amount (S\$)</b>	<b>14,707.15</b>	<b>7,845.24</b>	<b>6,861.91</b>	<b>46.66</b>

**INSPECTION**

Date of Assignment: 17/11/2022

Date Inspected: 22/11/2022 Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens)  
209 Pandan Gardens  
Singapore 609339

Estimated Period of Repair: 5.0 days

**Adjuster:** MARCUS CHUA**Manager:** XinYu

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 08 Dec 2022)
<b>Parts:</b> 143	KIA CERATO 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SNG9403J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*C&C BADGE	Necessary	50.00 FS	*50.00 FS
2	1		*SUNDRIES	Necessary	50.00 FS	*30.00 FS
3	1		*COVER -RR BUMPER	Dented	651.00 FS	*651.00 FS
4	1		*COVER -RR BUMPER LWR	Cracked	193.00 FS	*193.00 FS
5	1		*COVER -RR BUMPER UNDER ,LH	Twisted	33.00 FS	*33.00 FS
6	10		*CLIP	Necessary	10.00 FS	*10.00 FS
7	1		*COVER -RR BUMPER FOG LAMP ,LH	Twisted	39.00 FS	*39.00 FS
8	1		*LAMP ASSY -SIDE T/SIGNAL ,LH	Cracked	201.00 FS	*201.00 FS
9	1		*ULTRASONIC SENSOR ASSY -BWS	N/S Shorted	326.00 FS	*163.00 FS
10	1		*EXTN WIRING ASSY -BWS	Not Necessary	207.00 FS	*- FS
11	1		*BRACKET -ASSY RR BPR SIDE UPR ,RH	Not Necessary	26.00 FS	*- FS
12	1		*BRACKET -ASSY RR BPR SIDE UPR ,LH	Not Necessary	31.00 FS	*- FS
13	1		*BEAM -RR BUMPER	Not Necessary	318.00 FS	*- FS
14	2		*BRACKET -RR BPR UPR MTG	Not Necessary	84.00 FS	*- FS
15	1		*BRACKET -RR BEAM LWR ,CTR	Not Necessary	6.00 FS	*- FS
16	2		*BRACKET -RR BEAM LWR MTG	Not Necessary	14.00 FS	*- FS
17	1		*STAY -RR BUMPER RH	Not Necessary	65.00 FS	*- FS
18	1		*STAY -RR BUMPER LH	Not Necessary	65.00 FS	*- FS
19	1		*PANEL ASSY -BACK	Repair	324.00 FS	*- FS
20	1		*W/STRIP-TRUNK LID OPNG	Not Necessary	100.00 FS	*- FS
21	1		*LATCH ASSY -TRUNK LID	Not Necessary	112.00 FS	*- FS
22	1		*TRIM ASSY -RR TRANSVERSE	Not Necessary	41.00 FS	*- FS
23	1		*EMBLEM -KIA	Necessary	38.00 FS	*38.00 FS
24	1		*EMBLEM -CERATO	Necessary	28.00 FS	*28.00 FS
25	1		*EMBLEM -GT LINE	Necessary	45.00 FS	*45.00 FS
26	1		*PANEL ASSY -TRUNK LID	Dented / Bent	1,491.00 FS	*1,491.00 FS
27	1		*SPOILER -RR	Repair	257.00 FS	*- FS
28	1		*REAR BUMPER PROTECTOR (ACCESSORIES)	Necessary	150.00 FS	*150.00 FS

F=Franchise part. S=SpcNett.

<b>Total Parts (\$\$)</b>	<b>4,955.00</b>	<b>3,122.00</b>
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO APPLY SEALANT KIT ON NEW PANEL	New	240.00	80.00
2	TO APPLY ANTI CORROSION ON REAR ACCIDENT AFFECTED AREAS	New	200.00	100.00
3	TO TRANSFER TRUNK LID COMPONENT AND MECHANISM PARTS	New	640.00	320.00
4	TO REMOVE AND REINSTALL TRIMING AND CAPERTING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS	New	640.00	0.00
5	TO CHECK AND TEST REVERSE SENSOR	New	100.00	100.00
6	TO REPLACED TRUNK LID PNL ,REAR BUMPER ,REINFORCEMENT ,ETC TO CUT AND RE-WELD REAR END PANEL STRAIGHTEN ,REFORM ,ALIGN ON REAR ACCIDENT AFFECTED AREAS	New	3,840.00	1,600.00
7	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS	New	2,750.00	1,650.00
8	TO CONDUCT DIAGNOSTIC CHECK BY KDS AND CLEAR TROUBLE CODE	New	280.00	280.00
9	CHECK WIRING & ELECTRICAL SYSTEM	New	100.00	80.00
<b>Gross Labour Cost (\$\$)</b>			<b>8,790.00</b>	<b>4,210.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >