

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22011573/RQCE2**Date:** 03/05/2023REFERENCE

Insured/Claimant:	ANKIT SHARMA	Policy No:	2100443365-06	
Date of Loss:	14/11/2022	Nature of Claim:	OD	Claim No: 6431668846SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKX5735Z		Engine No:	CZC288938
Make & Model:	AUDI A3 SB, 1.4 TFSI AMBIENTE (A)		Chassis No:	WAUZZZ8V1GA044303
Reg. Date:	18/12/2015 (Man. Year: 2015)		Odometer:	100670 km
Colour:	Black			
Engine Capacity:	1395 cc			
Market Value/New Car Price:	S\$59,000.00			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	31,365.00	13,380.40	17,984.60	57.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	17,634.00	8,224.00	9,410.00	53.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	48,999.00	21,604.40	27,394.60	55.91
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	48,399.00	21,004.40	27,394.60	56.60
+ GST 8.00/8.00% (S\$)	3,871.92	1,680.35	2,191.57	56.60
Nett Amount (S\$)	52,270.92	22,684.75	29,586.17	56.60

INSPECTION

Date of Assignment:	17/11/2022	
Date Inspected:	16/11/2022	Inspected At: 24 Benoi Sector Singapore 629857 Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	9.0 days	

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,146.00 FS	*1,716.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	195.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	175.00 FS	*- FS
4	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	122.00 FS	*- FS
5	1		*FRONT BUMPER GUIDE SECTION - LH	Cracked	71.00 FS	*56.48 FS
6	1		*FRONT FENDER - LH	Bent	954.00 FS	*763.20 FS
7	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	75.00 FS	*- FS
8	1		*FRONT FENDER BRACKET - LH	Necessary	56.00 FS	*44.40 FS
9	1		*FRONT FENDER RIVET (8PCS)	Necessary	31.00 FS	*24.32 FS
10	1		*FRONT FENDER CLOSING ELEMENT	Bent	68.00 FS	*54.24 FS
11	1		*FRONT FENDER BRACE	Bent	107.00 FS	*85.60 FS
12	1		*FRONT FENDER BRACKET - LH	Not Necessary	31.00 FS	*- FS
13	1		*FRONT FENDER CLOSING ELEMENT - LH	Not Necessary	37.00 FS	*- FS
14	1		*FRONT WHEEL HOUSING LINER - LH	Deformed	183.00 FS	*146.40 FS
15	1		*HEADLIGHT GAS DISCHARGE LAMP - LH	Cracked	2,810.00 FS	*2,248.00 FS
16	1		*LIFT CYLINDER - LH	Not Necessary	211.00 FS	*- FS
17	1		*LIFT CYLINDER HOSE	Not Necessary	204.00 FS	*- FS
18	1		*FRONT EXTERIOR WING MIRROR MOUNTING - LH	Cracked	1,130.00 FS	*904.00 FS
19	1		*FRONT WING MIRROR CAP - LH	Missing	180.00 FS	*143.60 FS
20	1		*FRONT WING MIRROR GLASS - LH	Not Necessary	239.00 FS	*- FS
21	1		*FRONT WINDOW CORNER TRIM - LH	Scratched	51.00 FS	*40.40 FS
22	1		*FRONT WINDOW GUIDE - LH	Scratched	467.00 FS	*373.60 FS
23	1		*FRONT WINDOW SLOT SEAL TRIM STRIP - LH	Scratched	302.00 FS	*241.20 FS
24	1		*FRONT WINDOW CHROME ROOF MOLDING - LH	Scratched	665.00 FS	*531.60 FS
25	1		*FRONT WINDOW WATER DEFLECTOR STRIP - LH	Not Necessary	75.00 FS	*- FS
26	1		*FRONT DOOR WINDOW - LH	Not Necessary	257.00 FS	*- FS
27	1		*FRONT SIDE PANEL - LH	Repair	3,734.00 FS	*- FS
28	1		*FRONT WINDOW SILL TRIM STRIP	Not Necessary	140.00 FS	*- FS
29	1		*FRONT WINDOW STONE CHIP GUARD - LH	Not Necessary	82.00 FS	*- FS
30	1		*ADHESIVE TAPE	Not Necessary	59.00 FS	*- FS
31	1		*AIRBAG / CHILDS SEAT STICKER	Not Necessary	27.00 FS	*- FS
32	1		*FRONT ALUMINIUM RIM	Scratched	1,303.00 FS	*1,042.40 FS
33	1		*FRONT ALUMINIUM RIM RUBBER VALVE	Necessary	4.00 FS	*2.96 FS
34	1		*FRONT ASSEMBLY CARRIER	Bent	1,108.00 FS	*886.40 FS
35	1		*BONDED RUBBER BUSHES - UPPER / LOWER	Bent	179.00 FS	*142.80 FS
36	1		*LOWER CONTROL ARM - LH	Bent	394.00 FS	*314.80 FS
37	1		*STABILIZER	Not Necessary	452.00 FS	*- FS
38	1		*FRONT WHEEL BEARING HOUSING	Bent	628.00 FS	*502.40 FS
39	1		*FRONT WHEELHUB BEARING	Bent	554.00 FS	*443.20 FS
40	1		*GUIDE JOINT	Bent	137.00 FS	*109.60 FS
41	1		*COUPLING ROD	Not Necessary	105.00 FS	*- FS
42	1		*GAS SHOCK ABSORBER	Not Necessary	282.00 FS	*- FS
43	1		*DRIVE SHAFT - LH	Not Necessary	1,521.00 FS	*- FS
44	1		*FRONT STEERING GEAR	Not Necessary	5,552.00 FS	*- FS
45	1		*TRACK ROD	Bent	99.00 FS	*78.56 FS
46	1		*TIE ROD END - LH	Bent	126.00 FS	*100.40 FS
47	1		*ACRYLIC SEALANT	Not Necessary	180.00 FS	*- FS
48	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
49	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
50	1		*METAL FILLER POWDER	Not Necessary	280.00 FS	*- FS
51	1		*SUNDRIES	Necessary	800.00 FS	*238.64 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*WASH WATER RESERVOIR (Supplementary)	Deformed	226.00 FS	*180.40 FS
53	1		*FRONT RIM - RHS (Supplementary)	Scratched	1,303.00 FS	*1,042.40 FS
54	1		*REAR 1/4 GLASS CHROME TRIM - LH (Supplementary)	Necessary	293.00 FS	*234.00 FS
55	1		*HEADLIGHT POWER MODULE (Supplementary)	Faulty	635.00 FS	*507.60 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	31,365.00	13,380.40
--------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO REMOVE AND REINSTALL LHS FRONT SEAT ASSY, AB PILLAR TRIMS, SILL TRIMS, CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS	New	1,800.00	0.00
4	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR	New	280.00	280.00
5	TO RENEW LHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME	New	2,800.00	2,800.00
6	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. TO CUT OUT AND WELD LHS SILL PANEL. TO REPAIR LHS FRONT DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,500.00	1,500.00
7	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET, LHS FRONT DOOR, LHS ROOF CHANNEL, LHS SILL PANEL AND DOOR ENTRANCE	New	5,500.00	2,200.00
8	TO INSTALL SOLAR FILM ON LHS FRONT DOOR WINDOW GLASS	New	400.00	0.00
9	TO RENEW LHS FRONT RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	520.00	520.00
10	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	384.00
11	TO RENEW RHS FRONT RIM (Supplementary)	New	40.00	40.00
12	TP REPAIR LHS SILL PANEL (Supplementary)	New	700.00	250.00
Gross Labour Cost (S\$)			17,634.00	8,224.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >