

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG22011574/RNCE2**Date:** 12/01/2023**REFERENCE**

Insured/Claimant:	CHEN SIEW LOON	Policy No:	1900101502	
Date of Loss:	12/11/2022	Nature of Claim:	OD	Claim No: 3317687585SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SML5865X</b>		
Make & Model:	AUDI A3 SPORTBACK, 999cc TFSI S TRONIC (LED) (A)	Engine No:	CHZC29706
Reg. Date:	28/05/2019 (Man. Year: 2019)	Chassis No:	WAUZZZ8V1KA076726
Colour:	Red	Odometer:	52947 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$101,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,396.00	2,274.00	2,122.00	48.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,422.00	1,522.00	900.00	37.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>6,818.00</b>	<b>3,796.00</b>	<b>3,022.00</b>	<b>44.32</b>
<b>+ GST 7.00/7.00% (S\$)</b>	477.26	265.72	211.54	44.32
<b>Nett Amount (S\$)</b>	<b>7,295.26</b>	<b>4,061.72</b>	<b>3,233.54</b>	<b>44.32</b>

**INSPECTION**

Date of Assignment:	17/11/2022	
Date Inspected:	16/11/2022	Inspected At: 281 Alexandra Road Singapore 159938 Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	3.0 days	

**Adjuster:** MOHD RASUL**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,201.00 FS	*1,760.80 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	201.00 FS	*- FS
3	2		*REAR BUMPER LOCKING MECHANISM - LH / RH	Not Necessary	32.00 FS	*- FS
4	2		*REAR WHEEL HOUSING LINER ADAPTER - LH / RH	Not Necessary	84.00 FS	*- FS
5	1		*REAR BUMPER SPOILER	Not Necessary	264.00 FS	*- FS
6	2		*REAR BUMPER REFLECTOR - LH / RH	Not Necessary	68.00 FS	*- FS
7	1		*REAR BUMPER SIDE REINFORCEMENT	Bent	642.00 FS	*513.20 FS
8	2		*REAR BUMPER BRACKET - LH / RH	Not Necessary	63.00 FS	*- FS
9	2		*REAR PARKING AID SENSOR - INNER / OUTER	Not Necessary	531.00 FS	*- FS
10	4		*REAR PARKING AID SEAL RING	Not Necessary	10.00 FS	*- FS
11	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
					<b>Total Parts (\$\$)</b>	<b>4,396.00      2,274.00</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND TRANSFER REAR PARKING AID	New	280.00	280.00
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
3	TO RESPRAY REAR BUMPER	New	900.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,422.00</b>	<b>1,522.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >