

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22011577/ANP3E2**Date:** 21/12/2022REFERENCEHandling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00037032209

**Claimant Vehicle  
No :** SMV5532D**Insured  
Vehicle No :** SKH6927P

Date of Loss: 16/11/2022

Nature of Claim: TP

Claim  
No: SNM22D208255/C02/KHONGLHDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMV5532D**

Make &amp; Model: HYUNDAI I30 PDE, 1.4 T-GDI DCT (A)

Engine No: G4LDKD073679

Reg. Date: 15/11/2019 (Man. Year: 2019)

Chassis No: TMAH3513VLJ115226

Colour: White

Odometer: 65658 km

Engine Capacity: 1353 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,420.40	2,694.80	3,725.60	58.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,780.00	1,040.00	740.00	41.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,200.40</b>	<b>3,734.80</b>	<b>4,465.60</b>	<b>54.46</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,900.00</b>		
<b>(S\$)</b>	8,200.40	2,900.00	5,300.40	64.64
<b>+ GST 7.00/7.00% (S\$)</b>	574.03	203.00	371.03	64.64
<b>Nett Amount (S\$)</b>	<b>8,774.43</b>	<b>3,103.00</b>	<b>5,671.43</b>	<b>64.64</b>

INSPECTION

Date of Assignment: 18/11/2022

Date Inspected: 17/11/2022 Inspected At:

Twincar Automotive Pte Ltd (Kaki Bukit)  
BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB  
Singapore 417921

Estimated Period of Repair: 4.0 days

**Adjuster:** ADRIAN LING**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 21 Dec 2022)
<b>Parts:</b>	144	HYUNDAI I30 PDE 1.4 T-GDI DCT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMV5532D)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	837.00 FL	*- FL
2	2		*FRONT BUMPER SIDE RETAINER L/R	Not Necessary	158.00 FL	*- FL
3	1		*FRONT LH DOOR SIDE MIRROR ASSY	Cracked	1,337.00 FL	*1,085.00 FL
4	1		*FRONT LH FENDER	Dented	788.00 FL	*788.00 FL
5	1		*FRONT LH FENDER INNER SHIELD	Torn	225.00 FL	*225.00 FL
6	1		*FRONT LH KNUCKLE ARM	Not Necessary	900.00 FL	*- FL
7	1		*FRONT LH KNUCKLE ARM BEARING	Damaged	453.00 FL	*258.00 FL
8	1		*FRONT LH LOWER ARM	Not Necessary	545.00 FL	*- FL
9	1		*FRONT LH SHOCK ABSORBER	Not Necessary	509.00 FL	*- FL
10	1		*FRONT LH SPORT RIM	Cut	1,338.00 FN	*750.00 F
11	1		*FRONT LH STABILIZER LINK	Not Necessary	75.00 FL	*- FL
12	1		*FRONT LH TIE ROD END	Not Necessary	73.00 FL	*- FL
13	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
14	1		*FRONT LH 205/55ZR16 TYRE	Not Necessary	500.00 FS	*- FS
15	1		*SET FRONT LH FENDER INNER SHIELD CLIPS	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

<b>Sub Total (\$\$)</b>	<b>7,868.00</b>	<b>3,166.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	1,180.00	471.20
<b>- Nett Item Discount on N Items 20.00/0.00% (\$\$)</b>	267.60	0.00
<b>Total Parts (\$\$)</b>	<b>6,420.40</b>	<b>2,694.80</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHANGE FRONT SUSPENSION PARTS, ABSORBER, LOWER ARM, KNUCKLE ARM, WHEEL BEARING, BEARING HUB, DRIVE SHAFT, ANTI-ROLL BAR, TOP-ARM AND STEERING RACK AND PINION	New	280.00	80.00
2	TO ROAD TEST DRIVING, CHECK AND RESETTNG WHEEL ALIGNMENTS SYSTEM	New	100.00	80.00
3	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	New	700.00	500.00
4	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	600.00	350.00
5	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	100.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,780.00</b>	<b>1,040.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >