



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMB 51M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	SKIRT DOOR PANEL R12	BENT	1,800.00	1,800.00
1	RADIATOR DOOR FRAME	BENT	1,000.00	1,000.00
1	SIDE GLASS R7 5MM	SMASHED	600.00	600.00
1	COMPARTMENT HINGE LHS	BENT	190.00	190.00
1	COMPARTMENT HINGE RHS	BENT	190.00	190.00
2	GAS SPRING 0400N 21"	BENT	168.00	168.00
6	SEALANT	NECESSARY	240.00	240.00
	LESS 10% DISCOUNT		-	-418.80
			4,188.00	3,769.20
	<b><u>LABOUR</u></b>			
	TO DISMANTLE & REPLACE : ITEM NOS 1-7.		3,250.00	2,275.00
	TO REMOVE & INSTALL PARTS SO AS TO PERFORM REPAIR WORKS: OS REAR LAST PANEL.}		1,950.00	-
	SPRAY PAINTING : OS REAR LAST PANEL ,RADIATOR DOOR.}		1,280.00	1,080.00
			6,480.00	3,355.00
	<b>GRAND TOTAL</b>		<b>10,668.00</b>	<b>7,124.20</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>7,124.20</b>

Report Ref No. CS/FCI22011584/Gny3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.