



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 3812L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEEP CUT	578.10	578.10
1	FRONT FENDER (LH SIDE)	DENTED / BENT	789.10	789.10
1	FRONT WHEEL ARCH MOULDING (LH SIDE)	GRAZED	345.60	345.60
1	FRONT BUMPER SIDE RETAINER (LH SIDE)	NOT NECESSARY	57.20	-
1	FRONT WHEEL GARNISH INNER (LH SIDE)	DEFORMED /TORN	192.10	192.10
1	FRONT FENDER INNER IMPACT SPONGE (LH SIDE)	NOT NECESSARY	55.70	-
	LESS 10% DISCOUNT		-201.78	-
	LESS 25% DISCOUNT		-	-476.23
			1,816.02	1,428.67
	<u>SPECIAL NETT ITEMS</u>			
10	SET FRONT BUMPER CLIP @\$5.00 (SN)	NECESSARY	50.00	50.00
1	FENDER AIR VENT TRIM (SN)	TO REPAIR SEE LABOUR	150.00	-
1	FRONT HYBRID EMBLEM (SN)	NECESSARY	85.00	85.00
1	FRONT RIM (LH SIDE) (SN)	NOT NECESSARY	650.00	-
1	MIRROR COVER /LH SIDE (SN)	NOT NECESSARY	150.00	-
			1,085.00	135.00
	<u>LABOUR</u>			
	TO DISMANTLE ,REPAIR ,CUT ,WELD ,REPLACE.INCLUSIVE OF THE REPAIR OF FENDER AIR VENT TRIM .		800.00	300.00
	SPRAY PAINTING .		750.00	450.00
			1,550.00	750.00
	GRAND TOTAL		4,451.02	2,313.67
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,850.00

Report Ref No. CS/AGI22011585/Uny3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.