

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIS22011588/ANY3Q2**Date:** 27/12/2022REFERENCE

Handling Insurer: Allianz Insurance Singapore Pte. Ltd.

Policy No:

Claimant Vehicle No : GBK6421Y**Insured Vehicle No :** XD4144L

Date of Loss: 15/11/2022

Nature of Claim: TP Claim No: 2022 22008188FR

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBK6421Y**

Make & Model: KIA K2500, 2.5 D 6M/T (M)

Engine No: D4CBL019759

Reg. Date: 29/09/2020 (Man. Year: 2000)

Chassis No: KNCSJX76LL7454873

Colour: White

Odometer: 92528 km

Engine Capacity: 2497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C

Rear Tyre Size: 145 R13C

Front Left Side: Falken 6 mm

Rear Left Side: Kumho 6 mm

Front Right Side: Falken 6 mm

Rear Right Side: Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,848.95	7,373.86	8,475.09	53.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,300.00	2,560.00	1,740.00	40.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,148.95	9,933.86	10,215.09	50.70
Approved Total (Overridden) (S\$)		7,900.00		
(S\$)	20,148.95	7,900.00	12,248.95	60.79
+ GST 7.00/7.00% (S\$)	1,410.43	553.00	857.43	60.79
Nett Amount (S\$)	21,559.38	8,453.00	13,106.38	60.79

INSPECTION

Date of Assignment: 17/11/2022

Date Inspected: 18/11/2022 Inspected At:

N-51 Automotive Pte Ltd (HQ)

BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB
Singapore 417921

Estimated Period of Repair: 9.0 days

Adjuster: ADRIAN LING**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 27 Dec 2022)	
Parts:	N/A	KIA K2500 2.5 D 6M/T (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBK6421Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Dented	397.00 FL	*397.00 FL
2	1		*FRONT BONNET KIA LOGO EMBLEM	Necessary	72.00 FL	*72.00 FL
3	1		*FRONT BONNET GRILLE C/W MOULDING	Cracked	278.00 FL	*278.00 FL
4	2		*FRONT BONNET HINGE L/R	Not Necessary	144.00 FL	*- FL
5	1		*FRONT BONNET LOCK	Damaged	56.00 FL	*56.00 FL
6	1		*FRONT BUMPER	Deformed	419.70 FL	*419.70 FL
7	2		*FRONT BUMPER FOGLAMP COVER L/R	Not Necessary	44.00 FL	*- FL
8	1		*FRONT BUMPER LOWER GRILLE	Deformed	56.00 FL	*56.00 FL
9	1		*FRONT BUMPER LOWER REINFORCEMENT	Dented	248.00 FL	*248.00 FL
10	1		*FRONT BUMPER REINFORCEMENT	Dented	355.00 FL	*355.00 FL
11	2		*FRONT BUMPER SIDE HOLDER BRACKET L/R	Necessary	83.60 FL	*83.60 FL
12	1		*FRONT BUMPER UPPER GRILLE	Cracked	56.00 FL	*56.00 FL
13	2		*FRONT HEADLAMP CLIPS L/R	Necessary	11.00 FL	*11.00 FL
14	2		*FRONT HEADLAMP L/R	Cut	642.40 FL	*642.40 FL
15	1		*FRONT WASHER TANK	Deformed	101.00 FL	*101.00 FL
16	1		*FRONT WASHER PANEL	Repair	190.00 FL	*- FL
17	1		*REAR END PANEL	Dented	3,403.00 FL	*595.00 FL
18	1		*REAR NUMBER PLATE LAMP	Not Necessary	38.00 FL	*- FL
19	1		*REAR TAILGATE	Distorted	1,268.00 FL	*1,050.00 FL
20	1		*REAR TAILGATE FLIP LOCK HANDLE L/R	N/S Bent	197.40 FL	*98.70 FL
21	3		*REAR TAILGATE HINGES	Not Necessary	165.00 FL	*- FL
22	2		*REAR TAILLAMP L/R	Cracked	448.00 FL	*448.00 FL
23	2		*REAR TAILLAMP PANEL L/R	Repair	517.40 FL	*- FL
24	2		*REAR TAILLAMP PANEL RUBBER STOPPER L/R	Not Necessary	21.00 FL	*- FL
25	14		*SIDE GATE HINGES L/R	Not Necessary	770.00 FL	*- FL
26	1		*SIDE GATE L/R	N/S Dented	3,584.00 FL	*1,348.00 FL
27	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
28	1		*FRONT NUMBER PLATE	Damaged	35.00 FS	*35.00 FS
29	1		*FRONT NUMBER PLATE HOLDER	Deformed	50.00 FS	*30.00 FS
30	1		*REAR NUMBER PLATE	Dented	35.00 FS	*35.00 FS
31	1		*REAR NUMBER PLATE HOLDER	Deformed	50.00 FS	*30.00 FS
32	1		*SET REAR REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
33	1		*SET REAR REVERSE SENSOR BRACKET HOLDER	Necessary	90.00 FS	*50.00 FS
34	1		*REAR TAILGATE 13 PAX STICKER	Necessary	25.00 FS	*15.00 FS
35	1		*REAR TAILGATE 70KM/H STICKER	Necessary	25.00 FS	*15.00 FS
36	1		*REAR TAILGATE DETAIL STICKER	Necessary	250.00 FS	*150.00 FS
37	1		*REAR TAILGATE UPPER RUBBER PAD	Not Necessary	200.00 FS	*- FS
38	1		*REAR TAILGATE WARNING SIGN STICKER	Necessary	80.00 FS	*20.00 FS
39	1		*REAR UNDER BUMPER	Dented	1,300.00 FS	*900.00 FS
40	2		*REAR UNDER BUMPER BRACKET L/R	Not Necessary	600.00 FS	*- FS
41	2		*SIDE GATE DETAIL STICKER L/R	Necessary	600.00 FS	*180.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Sub Total (S\$)	17,205.50	8,005.40
				- List Item Discount on L Items 10.00/10.00% (S\$)	1,356.55	631.54
				Total Parts (S\$)	15,848.95	7,373.86

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING ,RESETTING HEADLAMP FOCUSING AND REWIRE FOR PARKING SENSOR	New	80.00	80.00
2	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,900.00	1,200.00
3	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	2,200.00	1,200.00
4	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	80.00
Gross Labour Cost (\$\$)			4,300.00	2,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >