



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNG 873U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	BUCKLED / DENTED	683.80	542.00
1	REAR BUMPER TOWING COVER	SERVICEABLE	40.00	-
1	REAR BUMPER REFLECTOR RH	SERVICEABLE	42.70	-
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	106.10	-
1	REAR BUMPER REINFORCEMENT	BENT	563.10	332.70
1	REAR END PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 25% DISCOUNT		-358.93	-218.67
			1,076.77	656.03
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	REAR BUMPER REVERSE SENSOR (SN)	SERVICEABLE	300.00	-
			350.00	50.00
<u>LABOUR</u>				
	LABOUR CHARGES TO REMOVE, REPLACE, REFIX & READJUST REAR ACCIDENT AREAS.		500.00	200.00
	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREAS.		600.00	200.00
	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.		100.00	50.00
	TO TUFF KOTE & UNDERSEAL MATERIALS.	NOT NECESSARY	100.00	-
	TO CHECK WIRING & ELECTRICAL SYSTEM.		100.00	15.00
			1,400.00	465.00
GRAND TOTAL			2,826.77	1,171.03

RECOMMENDED COST OF REPAIRS			1,171.03
------------------------------------	--	--	-----------------

Report Ref No. CS/SMR22011589/Kwy3m4

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.