

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/EGI22011590/GWY3E2**Date:** 14/02/2023REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** SG5794Y**Insured Vehicle No :** YP2380J

Date of Loss: 16/11/2022

Nature of Claim: TP

Claim No: CDMCG22002470

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SG5794Y**

Make &amp; Model: MAN A95, 10.5 D (A)

Engine No: 50344041794398

Reg. Date: 19/08/2016 (Man. Year: 2016)

Chassis No: WMAA95ZZ7G7003359

Colour: Green

Odometer: 500689 km

Engine Capacity: 10518 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5

Rear Tyre Size: 275/70 R22.5 (D)

Front Left Side: Firenza 6 mm

Rear Left Side: Firenza 6/6 mm

Front Right Side: Firenza 6 mm

Rear Right Side: Firenza 6/6 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>         | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                         | 1,320.00          | 1,188.00          | 132.00            | 10.00         |
| Miscellaneous Items           | 0.00              | 0.00              | 0.00              |               |
| Labour                        | 5,525.00          | 2,580.00          | 2,945.00          | 53.30         |
| Paintwork Labour              | 0.00              | 0.00              | 0.00              |               |
| Towing                        | 0.00              | 0.00              | 0.00              |               |
| <b>Gross Total (S\$)</b>      | <b>6,845.00</b>   | <b>3,768.00</b>   | <b>3,077.00</b>   | <b>44.95</b>  |
| <b>+ GST 7.00/7.00% (S\$)</b> | 479.15            | 263.76            | 215.39            | 44.95         |
| <b>Nett Amount (S\$)</b>      | <b>7,324.15</b>   | <b>4,031.76</b>   | <b>3,292.39</b>   | <b>44.95</b>  |

INSPECTION

Date of Assignment: 17/11/2022

Date Inspected: 18/11/2022 Inspected At:

TOWER TRANSIT SINGAPORE PTE LTD (MANDAI DEPOT) (HQ)  
310 Mandai Rd  
Singapore 779404

Estimated Period of Repair: 4.0 days

**Adjuster:** XING GUO QIANG**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |  |  |
|----------------------|--|--|
| <b>Part Source:</b>  | (Last Synchronised: 14 Feb 2023)   |  |
| <b>Parts:</b>        | N/A  | MAN A95 10.5 D (A) (Model not available in database) |
| <b>Labour:</b>       | Repairer's   | (Price-denominated Standard List)                    |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SG5794Y)   |  |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |  |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.   |  |

### Recommended Parts

| No. | Qty | Part No. | Particulars                        | Condition | Repairer's  | Amount          |
|-----|-----|----------|------------------------------------|-----------|---|-----------------|
| 1   | 1   |          | *NS REAR LAMP COVER                | Cracked   | 800.00 F  | *800.00 FL      |
| 2   | 2   |          | *REAR LAMP STOP ASSY LED (RED)     | Cracked   | 220.00 F  | *220.00 FL      |
| 3   | 1   |          | *REAR SIGNAL LAMP ASSY LED (CLEAR) | Cracked   | 300.00 F  | *300.00 FL      |
|     |     |          |                                    |           | <b>Sub Total (\$\$)</b>                                   | <b>1,320.00</b> |
|     |     |          |                                    |           | <b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b> | <b>0.00</b>     |
|     |     |          |                                    |           | <b>Total Parts (\$\$)</b>                                 | <b>1,320.00</b> |
|     |     |          |                                    |           |   | <b>1,188.00</b> |

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars   | Lab.Type | Repairer's      | Amount          |
|---------------------------------|---|----------|-----------------|-----------------|
| <b>Labour Items</b>             |   |          |                 |                 |
| 1                               | TO DISMANTLE & REPLACE : - ITEMS 1 - 3 }                                      | New      | 2,275.00        | 1,300.00        |
| 2                               | TO REMOVE & INSTALL PARTS SO AS TO PERFORM REPAIR WORKS : -<br>NS REAR DOME } | New      | 1,300.00        | 0.00            |
| 3                               | SPRAY PAINTING : - NS REAR LAMP COVER - NS REAR DOME                          | New      | 1,950.00        | 1,280.00        |
| <b>Gross Labour Cost (\$\$)</b> |   |          | <b>5,525.00</b> | <b>2,580.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >