



TY5 CONSULTANCY

(Registration No.: 53429875C)

Address : 50 Chin Swee Road #09-04, Thong Chai Building, Singapore 169874

Contact : +65 8788 5345 | Email Address : admin@ty5group.com.sg

*Our Services : Automotive Surveying | Vehicle Valuation
Motor Claims Investigation | Evaluation & Consultation*

Reference : TY5/TA/10149/3091/TP/10.22

Date : 20 October 2022

Vehicle no : PC 3091L

To: Silveray Pte Ltd
c/o 2 Kaki Bukit Ave 2
#01-36, Kaki Bukit Autohub
Singapore 417921

INVOICE

PARTICULARS

AMOUNT

Registration No. : PC 3091L
Date of accident : 16 October 2022
Make / Model : Toyota Hiace Van Turbo 4Dr (A)
Invoice No. : 10149

Being work done and services rendered as follows:

- ✓ Inspection of Vehicle
- ✓ Re-Inspection
- ✓ Appraisal Report
- ✓ 44 Colored Photographs
- ✓ Transport Charges

SGD 544.00

TOTAL SGD 544.00

Dollars: Five Hundred and Forty-Four Only

(Cheque should be crossed and make payable to " TY5 CONSULTANCY ")

TY5 CONSULTANCY



TY5 CONSULTANCY

(Registration No.: 53429875C)

Address : 50 Chin Swee Road #09-04, Thong Chai Building, Singapore 169874

Contact : +65 8788 5345 | Email Address : admin@ty5group.com.sg

*Our Services : Automotive Surveying | Vehicle Valuation
Motor Claims Investigation | Evaluation & Consultation*

Reference : TY5/TA/10149/3091/TP/10.22

Date : 20 October 2022

Vehicle no : PC 3091L

To: Silveray Pte Ltd
c/o 2 Kaki Bukit Ave 2
#01-36, Kaki Bukit Autohub
Singapore 417921

VEHICLE INSPECTION REPORT

Name of Workshop : Sheng Li Lai
Place of inspection : 2 Kaki Bukit Ave 2 #01-36, Kaki Bukit Autohub, Singapore 417921
Date of Accident : 16 October 2022
Date of Inspection : 19 October 2022

VEHICLE PARTICULAR

Registration No.	: PC 3091L	Chassis Frame No.	: JTFHT02P600154496
Make / Model	: Toyota Hiace Van Turbo 4Dr (A)	Engine No.	: 1KD2464132
Year of Registration	: 2014	Odometer Reading	: 243,979 KM
Class / Type	: Van	Colour	: Silver

VEHICLE CONDITION

General Condition	: Good	Steering	: Serviceable
Paintwork	: Good	Foot/ Parking Brake	: Serviceable

TYRE CONDITION

	<u>Size</u>	<u>Thread Balance</u>
Front L/H :	HANKOOK 195 R15C	7mm
Front R/H :	HANKOOK 195 R15C	7mm
Rear L/H :	HANKOOK 195 R15C	7mm
Rear R/H :	HANKOOK 195 R15C	7mm

* The above is an estimate of the remaining life of the tyre thread in percentages

COST OF REPAIR

	Repairer S\$	Adjuster S\$
Parts	\$ 5,172.05	\$ 3,459.46
Labour	\$ 3,190.00	\$ 2,630.00
	<u>\$ 8,362.05</u>	<u>\$ 6,089.46</u>

TY5 Recommendation

Lump Sum Repair :
\$ 4,850.00

Estimated Repair Duration :

7

working days (excluding Sat, Sun & Public Holidays)

NOTE : The information contained in these documents may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited.



TY5 CONSULTANCY

(Registration No.: 53429875C)

Address : 50 Chin Swee Road #09-04, Thong Chai Building, Singapore 169874

Contact : +65 8788 5345 | Email Address : admin@ty5group.com.sg

*Our Services : Automotive Surveying | Vehicle Valuation
Motor Claims Investigation | Evaluation & Consultation*

Reference : TY5/TA/10149/3091/TP/10.22
Date : 20 October 2022
Vehicle no : PC 3091L

ASSESSMENT SCHEDULE

<u>SN</u>	<u>Qty</u>	<u>Descriptions</u>	<u>Conditions</u>	<u>Repairer's Estimate</u>	<u>Surveyor's Revised</u>
<u>LIST ITEMS:-</u>					
1	1 pc	rear bumper	deformed	\$ 372.50	\$ 372.50
2	4 pcs	rear bumper support bracket @\$16.50	buckled	\$ 66.00	\$ 66.00
3	2 pcs	rear bumper side retainer @\$38.00	necessary	\$ 76.00	\$ 76.00
4	1 set	rear bumper clips	necessary	\$ 35.00	\$ 35.00
5	1 pc	tailgate	buckled	\$ 1,694.20	\$ 1,694.20
6	1 pc	tailgate logo emblem	necessary	\$ 67.10	\$ 67.10
7	1 pc	tailgate inner lock	jammed	\$ 235.40	\$ 235.40
8	1 pc	tailgate weatherstrip	cut	\$ 417.60	\$ 417.60
9	1 pc	tailgate outer garnish	unconfirmed	\$ 179.20	not affected
10	1 pc	rear windscreen moulding	necessary	\$ 165.00	\$ 165.00
11	1 set	rear end panel - complete	buckled	\$ 1,337.15	\$ 1,337.15
12	1 pc	rear floor panel	buckled	repair	repair
13	1 pc	r/h taillamp	unconfirmed	\$ 297.20	not affected
14	1 pc	r/h taillamp filler panel	unconfirmed	\$ 69.70	not affected
				\$ 5,012.05	\$ 4,465.95
		Less 25%			\$ 1,116.49
				\$ 5,012.05	\$ 3,349.46
<u>SPECIAL NETT ITEMS:-</u>					
15	1 set	reverse sensor	not working	\$ 300.00	\$ 250.00
16	1 pc	tailgate "60 km/h" sticker	necessary	\$ 30.00	\$ 25.00
17	1 pc	tailgate "emergency door" sticker	necessary	\$ 20.00	\$ 15.00
18	1 pc	tailgate "pull to open" sticker	necessary	\$ 20.00	\$ 15.00
19	1 roll	rear windscreen sealant	necessary	\$ 60.00	\$ 40.00
20	1 roll	rear end panel sealant	necessary	\$ 60.00	\$ 40.00
				\$ 160.00	\$ 110.00
Total				\$ 5,172.05	\$ 3,459.46



TY5 CONSULTANCY

(Registration No.: 53429875C)

Address : 50 Chin Swee Road #09-04, Thong Chai Building, Singapore 169874

Contact : +65 8788 5345 | Email Address : admin@ty5group.com.sg

*Our Services : Automotive Surveying | Vehicle Valuation
Motor Claims Investigation | Evaluation & Consultation*

Reference : TY5/TA/10149/3091/TP/10.22

Date : 20 October 2022

Vehicle no : PC 3091L

ASSESSMENT SCHEDULE

<u>SN</u>	<u>Qty</u>	<u>Descriptions</u>	<u>Conditions</u>	<u>Repairer's Estimate</u>	<u>Surveyor's Revised</u>
		B/F		\$ 5,172.05	\$ 3,459.46
1		To panel beat and renewal of all necessary damaged body parts		\$ 1,400.00	\$ 1,200.00
2		To check wiring and rewire		\$ 60.00	\$ 50.00
3		To remove and reinstall tailgate components		\$ 80.00	\$ 60.00
4		To remove and reinstall rear windscreen		\$ 150.00	\$ 120.00
5		To remove and reinstall rear boot upholstery		\$ 120.00	\$ 100.00
6		To remove and reinstall reverse sensor		\$ 140.00	\$ 100.00
7		To remove and reinstall rear exhaust muffler		\$ 120.00	\$ 100.00
8		To apply anti-rust		\$ 120.00	\$ 100.00
9		To putty and spray-paint of affected areas		\$ 1,000.00	\$ 800.00
				<u>\$ 3,190.00</u>	<u>\$ 2,630.00</u>

Total \$ 8,362.05 \$ 6,089.46



TY5 CONSULTANCY

(Registration No.: 53429875C)

Address : 50 Chin Swee Road #09-04, Thong Chai Building, Singapore 169874

Contact : +65 8788 5345 | Email Address : admin@ty5group.com.sg

*Our Services : Automotive Surveying | Vehicle Valuation
Motor Claims Investigation | Evaluation & Consultation*


Reference : TY5/TA/10149/3091/TP/10.22

Date : 20 October 2022

Vehicle no : PC 3091L

ASSESSMENT SUMMARY

Damages sustained were consistent with the subject vehicle being involved in a collision with another vehicle and the impact of the collision was delivered Squarely to the Rear portion of the vehicle.



(Please refer to the list and survey photographs as attached for more information)

ASSESSMENT RECOMMENDATIONS

COST OF REPAIR

	Repaierer S\$	Adjuster S\$
Parts	\$ 5,172.05	\$ 3,459.46
Labour	\$ 3,190.00	\$ 2,630.00
	<u>\$ 8,362.05</u>	<u>\$ 6,089.46</u>

TY5 Recommendation

Contract Lump Sum of \$ 4,850.00

Estimated Repair Duration : 7 working days
(excluding Sat, Sun & Public Holidays)

Enclosed No. Of Photograph : 44
(at the time of static inspection)

Our attached assessment schedule has been checked throughly by us against the actual damages sustained on the vehicle, and we recommend the replacement of parts and repair accordingly. We have adjusted the cost and the repaierer has agreed to undertake the repair at the recommended sum to a acceptable quality and standards. We have not given authorization and instruction to the repaierer to proceed with the repairs.

The survey was done on a **Without Prejudice Basis** and we are reverting the matter to you for a decision.

We thank you for engaging our services and we enclosed herewith our invoice no. 10149

TY5 CONSULTANCY

TERRENCE HONG
AUTOMOTIVE SURVEYOR

NOTE : *This revised estimate was from a visual inspection. Should there be any discrepancy or unseen items not listed in this survey, kindly notify the company via email only and follow up with a phone call, within Fourteen (14) days from the date hereof. Otherwise this revised amount shall be treated as valid.*

