

ASS. REC. BY:

REF: 004/AIS 2201595/DP2

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 7/P % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SNB 9956C Yr Regn: Spt 2021

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Cross Hybrid c.c. 1490

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 25384 T/Radio: Insured / Std / NI / NA

Eng/No: M15AY249322

C/No: JTDK BAB 220 L 006316

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/65 R11

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Dunlop

Front _____ Rear _____

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 15/11/2022 D.O.I. 17/11/2022

Survey held at CS Ing AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

R

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Call in SNB 9956C

22/2/2023 Franchise 7/P 7,742.78 with 5 days of rep

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Inve (\$

Survey Fee:

Transportation:

S + RS SI

Photos

Others

Report Format:

1. Service 2. Claims 3. P. & E. 4. In. 5. Out

C. S. ONG AUTO PTE LTD

Co. Reg. No.: 201408916W

7030, ANG MO KIO AVE 5, #B1-01 NORTHSTAR @ AMK, SINGAPORE 569880

TEL: 6484 1933 | FAX: 6481 1916

E-Mail: csongauto.claims@yahoo.com.sg

To: ALLIANZ

Att: Motor Claims Dept

ACCIDENT INVOLVING SNB8968D [YOUR INSURED] & SNB9956G [OUR CLIENT]
ON 15/11/2022.

ESTIMATED REPAIR COSTS FOR SNB9956G

MODEL : TOYOTA YARIS CROSS

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>	
1PC	TAILGATE <i>Denki</i> 1543.90	\$ 1,869.50	✓
1PC	TAILGATE CENTER BLACK GARNISH HH	\$ 725.10	X
1PC	TAILGATE CENTER GARNISH HH	\$ 460.70	X
1PC	TAILGATE LOGO HH	\$ 92.60	X
1PC	TAILGATE 'HYBRID' EMBLEM Hec 69.00	\$ 102.40	✓
1PC	TAILGATE 'YARIS CROSS' EMBLEM Hec	\$ 135.20	✓
1PC	TAILGATE WINDSCREEN MOULDING Hec 169.20	\$ 298.40	✓
1PC	TAILGATE SWITCH HH	\$ 290.20	X
1PC	TAILGATE INNER SWITCH HH	\$ 258.00	X
1PC	TAILGATE LOCK Denki	\$ 381.10	✓
2PCS	TAILGATE NO. PLATE LAMP LH / RH @ \$118.00 EACH HH	\$ 236.00	X
1PC	TAILGATE WEATHER STRIP <i>adjusted</i>	\$ 317.20	✓
1PC	TAILGATE INNER TRIM BOARD <i>mondy cradle</i> 551.00	\$ 1,002.00	✓
1PC	TAILGATE TOP SPOILER HH	\$ 892.40	X
1PC	TAILGATE HINGE LH / RH @ \$109.10 EACH HH	\$ 218.20	X
1PC	TAILGATE REVERSE CAMERA HH	\$ 990.90	X
2PCS	TAILGATE LAMP LH / RH @ \$619.00 EACH HH	\$ 1,238.00	X 492.5
2PCS	TAIL LAMP LH / RH @ \$928.10 EACH <i>o/s mondy cradle n/s HH</i>	\$ 1,856.20	✓
2PCS	TAIL LAMP LOWER BRACKET LH / RH @ \$198.00 EACH <i>o/s mondy cradle</i>	\$ 396.00	✓ 159.10
2PCS	TAIL LAMP PANEL LH / RH @ \$501.10 EACH HH <i>n/s HH</i>	\$ 1,002.20	X
1PC	REAR BUMPER <i>Denki</i> 503.04	\$ 1,384.50	✓
2PCS	REAR BUMPER SIDE RETAINER LH / RH @ \$89.20 EACH <i>SH</i>	\$ 178.40	X
1PC	REAR BUMPER CENTER BRACKET HH	\$ 329.50	X
1PC	REAR BUMPER LOWER LID <i>Denki</i> 541.10	\$ 819.10	✓
2PCS	REAR BUMPER REFLECTOR LH / RH @ \$98.00 EACH HH	\$ 196.00	X
2PCS	REAR BUMPER SENSOR @ \$298.10 EACH <i>SH Denki</i>	\$ 596.20	✓
2PCS	REAR BUMPER SENSOR HOLDER @ \$15.10 EACH Hec	\$ 30.20	✓
1PC	REAR BUMPER SENSOR WIRE HARNESS HH	\$ 1,680.10	X
1PC	REAR BUMPER SPONGE HP	\$ 298.00	X
1PC	REAR REINFORCEMENT BAR HP	\$ 1,298.00	X

1PC	REAR END PANEL <i>Dent</i>	696.30	\$ 1,429.40	✓
1PC	REAR END PANEL TOP GARNISH <i>money crack</i>		\$ 353.10	✓
1PC	REAR END PANEL SENSOR BUZZER <i>HH</i>		\$ 219.20	X
1PC	REAR END PANEL ANTENNA RECEIVER <i>broken</i>		\$ 247.60	✓
1PC	SPARE WHEEL PANEL <i>HH</i>		\$ 2,419.20	X
1PC	SPARE WHEEL PANEL TOP BOARD <i>HH</i>		\$ 619.00	X
1PC	SPARE WHEEL PANEL TOOL BOX <i>HH</i>		\$ 472.00	X
2PCS	REAR FENDER LH / RH @ \$2,791.20 EACH <i>HH</i>		\$ 5,582.40	X 871.30
2PCS	REAR FENDER INNER TRIM LH / RH @ \$1,490.00 EACH <i>o/s broken / HH</i>		\$ 2,980.00	✓
2PCS	REAR FENDER QUARTER GLASS MOULDING LH / RH @ \$129.00 <i>HH</i>		\$ 258.00	X
1PC	REAR EXHAUST PIPE <i>HH</i>		\$ 1,982.40	X
1PC	REAR EXHAUST MOUNTING <i>HH</i>		\$ 104.00	X
1PC	REAR EXHAUST HEAT SHIELD <i>HH</i>		\$ 198.00	X

7,657.04

5,742.78 =

PARTS SUM: \$ 36,436.60

PARTS LESS 25%: \$ 9,109.15

PARTS TOTAL: \$ 27,327.45

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY TAILGATE WINDSCREEN SEALANT <i>HH</i>	\$ 80.00	40/-
*	TO SUPPLY TAILGATE WINDSCREEN DAMPING SEAL <i>HH</i>	\$ 40.00	X
*	TO SUPPLY TAILGATE CENTER MOULDING CLIPS <i>HH</i>	\$ 50.00	X
*	TO SUPPLY REAR NO. PLATE & CASING <i>HH</i>	\$ 100.00	X
*	TO SUPPLY REAR BUMPER CLIPS <i>HH</i>	\$ 50.00	20/-
*	TO SUPPLY REAR BUMPER LOWER LID CLIPS <i>HH</i>	\$ 50.00	X
*	TO SUPPLY TAILGATE LAMP CLIPS <i>HH</i>	\$ 50.00	X
*	TO SUPPLY TAIL LAMP CLIPS <i>HH</i>	\$ 50.00	X
*	TO SUPPLY REAR END PANEL SEALANT <i>HH</i>	\$ 80.00	40/-
*	TO SUPPLY REAR END PANEL TOP GARNISH CLIPS <i>HH</i>	\$ 50.00	15/-
*	TO SUPPLY SPARE WHEEL PANEL SEALANT <i>HH</i>	\$ 80.00	X
*	TO SUPPLY REAR FENDER SEALANT <i>HH</i>	\$ 80.00	X
*	TO SUPPLY REAR FENDER QUARTER GLASS SEALANT <i>HH</i>	\$ 80.00	X
*	TO SUPPLY REAR FENDER QUARTER GLASS DAMPING SEAL <i>HH</i>	\$ 30.00	X
*	TO SUPPLY REAR FENDER INNER TRIM CLIPS <i>HH</i>	\$ 50.00	15/-
*	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILITATE REPAIRS	\$ 300.00	80/-
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$ 3,000.00	700/-
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	\$ 3,000.00	600/-
*	TO TUFF COAT DAMAGED AREAS	\$ 300.00	40/-
*	TO RNR TAILGATE WINDSCREEN TO FACILITATE REPAIRS	\$ 400.00	120/-

*	TO RNR TAILGATE MECHANISM TO FACILITATE REPAIRS	\$	200.00 60/-
*	TO RNR TAILGATE REVERSE CAMERA TO FACILITATE REPAIRS	\$	100.00 44
*	TO RNR REAR BUMPER SENSOR TO FACILITATE REPAIRS	\$	120.00 40/-
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	\$	200.00 30/-
*	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	\$	300.00 44
*	TO RNR EXHAUST & ATTACHEMNT PARTS TO FACILITATE REPAIRS	\$	120.00 44
*	TO RNR REAR FENDER QUARTER GLASS TO FACILITATE REPAIRS	\$	200.00 44

LABOUR & S/N TOTAL: \$ 9,160.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 36,487.45

P/P 7,742.78

17/11/2022 @ 1600w

NA Andrew

4/11/2022 P/P

Ign 5 days

LKK Auto

8

Check part prices.

Photo after repair

with damaged parts.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: