

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22011596/KYA3Q2**Date:** 17/07/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700028557
Claimant Vehicle No :	SNH268L	Insured Vehicle No :	GBG3002P
Date of Loss:	16/11/2022	Nature of Claim:	TP
		Claim No:	2990808297SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNH268L		
Make & Model:	TESLA MODEL 3 STANDARD RANGE, (A)	Engine No:	HIDDEN
Reg. Date:	17/11/2021 (Man. Year: 2021)	Chassis No:	LRW3F7FAXMC384827
Colour:	Metallic Pearl White	Odometer:	8073 km
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/45Z R18	Rear Tyre Size:	235/45Z R18
Front Left Side:	Michelin 9 mm	Rear Left Side:	Michelin 9 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,952.83	2,835.43	2,117.40	42.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,740.00	1,650.00	1,090.00	39.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,692.83	4,485.43	3,207.40	41.69
Approved Total (Overridden) (S\$)		3,550.00		
(S\$)	7,692.83	3,550.00	4,142.83	53.85
+ GST 7.00/7.00% (S\$)	538.50	248.50	290.00	53.85
Nett Amount (S\$)	8,231.33	3,798.50	4,432.83	53.85
+ Loss of Use (6.0 x S\$100.00/day) (S\$)		600.00		
(S\$)		4,398.50		
Liabe Amount (50.00%) (S\$)		2,199.25		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,201.25		

INSPECTION

Date of Assignment:	18/11/2022	Optima Werkz Pte Ltd (HQ)
Date Inspected:	18/11/2022 Inspected At:	10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint
Estimated Period of Repair:	6.0 days	Singapore 568047

Adjuster: KENNETH KONG

Manager: Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR RH	Bent	953.27 FL	*953.27 FL
2	1		*REAR DOOR WEATHERSTRIP RH	Serviceable	88.79 FL	*- FL
3	1		*REAR DOOR INNER TRIM BOARD RH	Serviceable	560.75 FL	*- FL
4	1		*REAR DOOR OUTER HANDLE RH	Serviceable	214.95 FL	*- FL
5	1		*REAR DOOR OUTER HANDLE SENSOR RH	Serviceable	27.10 FL	*- FL
6	1		*REAR DOOR WINDOW REGULATOR RH	Serviceable	224.30 FL	*- FL
7	1		*REAR DOOR OUTER MOULDING RH	Serviceable	92.91 FL	*- FL
8	1		*REAR DOOR FOAM PAD RH	Serviceable	9.35 FL	*- FL
9	1		*REAR DOOR INNER LOCK RH	Repair	33.64 FL	*- FL
10	1		*REAR FENDER RH	Bent	1,345.79 FL	*1,345.79 FL
11	1		*REAR FENDER QUARTER GLASS RH WITH MLDG	Mldg Necessary	280.37 FL	*280.37 FL
12	1		*REAR RIM RH	Dented	505.00 FL	*505.00 FL
13	1		*REAR RIM COVER RH	Dented	32.71 FL	*32.71 FL
14	1		*REAR BUMPER	Repair	766.00 FL	*- FL
15	1		*REAR BUMPER PARKING SENSOR	Serviceable	163.55 FL	*- FL
16	1		*REAR BUMPER PARKING SENSOR BRACKET	Serviceable	4.67 FL	*- FL
17	1		*REAR DOOR INNER TRIM BOARD CLIPS RH	Not Necessary	50.00 FS	*- FS
18	1		*REAR FENDER QUARTER GLASS SEALANT RH	Necessary	80.00 FS	*30.00 FS
19	1		*REAR BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					5,483.15	3,147.14
- List Item Discount on L Items 10.00/10.00% (S\$)					530.32	311.71
Total Parts (S\$)					4,952.83	2,835.43

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC	New	800.00	700.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR DOOR RH, REAR FENDER RH, REAR BUMPER & ETC	New	800.00	660.00
3	LABOUR CHARGES TO REMOVE & REINSTALLED REAR DOOR INNER MECHANISM & ETC. TO EFFECT REPLACE OF REAR DOOR RH	New	120.00	60.00
4	LABOUR CHARGES TO REMOVE & REPLACE REAR FENDER QUARTER GLASS, REAR QUARTER GLASS SEALANT	New	150.00	50.00
5	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER PARKING SENSOR & ETC	New	120.00	0.00
6	TO TUFF KOTE & UNDERSEAL MATERIALS	New	150.00	60.00
7	TO DIAGNOSIS FAULT CODE & RESET MEMORY	New	150.00	0.00
8	TO CHECK WIRING & ELECTRICAL SYSTEM	New	100.00	20.00
9	LABOUR CHARGES TO REMOVE & REFIX REAR FENDER INNER TRIM & CUSHION UPHOLSTERY SET & ETC. TO EFFECT REPLACE OF REAR FENDER RH	New	350.00	100.00
Gross Labour Cost (S\$)			2,740.00	1,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >