

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22011599/APA3Q2**Date:** 11/07/2023REFERENCE

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP0001094453
Claimant Vehicle No :	SMF5700U	Insured Vehicle No :	GBC9572S
Date of Loss:	16/11/2022	Nature of Claim:	TP
		Claim No:	202222008179

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF5700U		
Make & Model:	HONDA CIVIC, 1.5 TURBO VTI-S SR (A)	Engine No:	L15B73621181
Reg. Date:	14/06/2018 (Man. Year: 2018)	Chassis No:	MRHFC1660JT000012
Colour:	Blue	Odometer:	93547 km
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/50 R17	Rear Tyre Size:	215/50 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,892.76	4,720.56	3,172.20	40.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,680.00	1,860.00	820.00	30.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,572.76	6,580.56	3,992.20	37.76
Approved Total (Overridden) (S\$)		5,200.00		
(S\$)	10,572.76	5,200.00	5,372.76	50.82
+ GST 8.00/8.00% (S\$)	845.82	416.00	429.82	50.82
Nett Amount (S\$)	11,418.58	5,616.00	5,802.58	50.82
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,323.45		
Global Sum Settlement (S\$)		6,300.00		

INSPECTION

Date of Assignment:	17/11/2022	N-51 Automotive Pte Ltd (HQ)
Date Inspected:	17/11/2022 Inspected At:	BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT
		AUTOHUB
		Singapore 417921
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Jul 2023)
Parts:	143	HONDA CIVIC 1.5 TURBO VTI-S SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMF5700U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BOOTLID	Dented	684.50 FL	*684.50 FL
2	1	*REAR BOOTLID CIVIC EMBLEM	Necessary	31.50 FL	*31.50 FL
3	1	*REAR BOOTLID I-VTEC EMBLEM	Necessary	34.20 FL	*34.20 FL
4	1	*REAR BOOTLID LOGO EMBLEM	Necessary	28.00 FL	*28.00 FL
5	2	*REAR BOOTLID HINGES GARNISH L/R	Not Necessary	248.60 FL	*- FL
6	2	*REAR BOOTLID HINGES L/R	Not Necessary	98.40 FL	*- FL
7	2	*REAR BOOTLID INNER RUBBER STOPPER L/R	Not Necessary	19.60 FL	*- FL
8	1	*REAR BOOTLID INNER TRIM BOARD	Not Necessary	105.60 FL	*- FL
9	1	*REAR BOOTLID LOCK STRIKER	Not Necessary	49.20 FL	*- FL
10	1	*REAR BOOTLID MECHANISM LOCK	Damaged	84.90 FL	*84.90 FL
11	2	*REAR BOOTLID NUMBER PLATE LAMP L/R	Not Necessary	177.40 FL	*- FL
12	1	*REAR BOOTLID OUTER GARNISH	Cracked	268.00 FL	*268.00 FL
13	1	*REAR BOOTLID OUTER LOCK SWITCH	Not Necessary	128.00 FL	*- FL
14	2	*REAR BOOTLID REFLECTOR L/R	Cut	267.20 FL	*267.20 FL
15	1	*REAR BOOTLID WEATHERSTRIP	Cut	80.40 FL	*80.40 FL
16	1	*REAR BUMPER	Deformed	617.20 FL	*617.20 FL
17	2	*REAR BUMPER LOWER COVER (EXHAUST) L/R	Torn	120.80 FL	*120.80 FL
18	1	*REAR BUMPER LOWER LID (BLACK)	Deformed	198.10 FL	*198.10 FL
19	2	*REAR BUMPER REFLECTOR GARNISH L/R	Cut	63.00 FL	*63.00 FL
20	2	*REAR BUMPER REFLECTOR L/R	Cut	49.00 FL	*49.00 FL
21	1	*REAR BUMPER REINFORCEMENT	Deformed	288.40 FL	*288.40 FL
22	4	*REAR BUMPER REVERSE SENSOR	Damaged (2 PCS ONLY)	596.80 FL	*298.40 FL
23	4	*REAR BUMPER REVERSE SENSOR O RING	Necessary	60.00 FL	*60.00 FL
24	4	*REAR BUMPER REVERSE SENSOR HOLDER	Necessary	72.00 FL	*72.00 FL
25	1	*REAR BUMPER REVERSE SENSOR WIRE HARNESS	Not Necessary	87.40 FL	*- FL
26	2	*REAR BUMPER SIDE RETAINER L/R	Cracked	150.80 FL	*150.80 FL
27	1	*REAR BUMPER TOW HOOK COVER	Not Necessary	20.00 FL	*- FL
28	1	*REAR END PANEL	Dented	377.50 FL	*377.50 FL
29	1	*REAR END PANEL ANTENNA SENSOR	Cracked	80.40 FL	*80.40 FL
30	1	*REAR END PANEL BUZZLE SENSOR	Cracked	85.10 FL	*85.10 FL
31	1	*REAR END PANEL INNER TOP GARNISH	Cracked	70.30 FL	*70.30 FL
32	2	*REAR FENDER INNER TRIM BOARD L/R	Not Necessary	538.60 FL	*- FL
33	1	*REAR FLOOR PANEL TOP BOARD COVER	Torn	255.40 FL	*255.40 FL
34	2	*REAR TAILLAMP INNER PANEL L/R	Repair	137.80 FL	*- FL
35	2	*REAR TAILLAMP L/R	Cracked	596.80 FL	*596.80 FL
36	2	*REAR TAILLAMP LOWER BRACKET L/R	Cracked	38.80 FL	*38.80 FL
37	1	*REAR BOOTLID CAMERA	Not Necessary	800.00 FS	*- FS
38	1	*SET REAR BOOTLID INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
39	1	*REAR BOOTLID NUMBER PLATE	Not Necessary	25.00 FS	*- FS
40	1	*REAR BOOTLID NUMBER PLATE HOLDER	Not Necessary	50.00 FS	*- FS
41	1	*SET REAR BOOTLID OUTER GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
42	1	*REAR BOOTLID TOP SPOILER	Cracked	1,200.00 FS	*700.00 FS
43	1	*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	40.00 FS	*20.00 FS
44	2	*SET REAR FENDER INNER TRIM BOARD CLIPS L/R	Not Necessary	100.00 FS	*- FS
45	2	*SET REAR TAILLAMP CLIPS L/R	Necessary	50.00 FS	*20.00 FS
46	1	*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

7/11/23, 11:37 AM			Adjuster Report		
No.	Qty	Part No.	Particulars	Condition	Repairer's Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.					
				Sub Total (\$)	9,254.70 5,700.70
				- List Item Discount on L Items 20.00/20.00% (\$)	1,361.94 980.14
				Total Parts (\$)	7,892.76 4,720.56
Report was unsubmitted during this print-out.					

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TRANSFER REAR BOOTLID MECHANISM LOCK OUTER HANDLE REFLECTOR	New	80.00	60.00
2	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	80.00	80.00
3	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY CUSHION SEAT ,TRIM GARNISH ,TRIM LINER CARPET (TO FR)	New	100.00	60.00
4	TO RE-SPRAY PAINTING ON THE REAR BOOTLID ,REAR END PANEL,REAR FENDER (L/R) ,SPARE TYRE PANEL AND REAR BUMPER	New	1,300.00	800.00
5	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE ,BODY ALIGNEMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,000.00	800.00
6	TO APPLY ANTI RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	60.00
Gross Labour Cost (S\$)			2,680.00	1,860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >