

ASS. REC. BY:

REF:

ASM/220116001kp

C

Kenneth

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD/TP/WS/TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s Thian Hwy Hwy

of 2958

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$130k

IDAC Accident Rport: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: STG 1164X Yr Regn: 03, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: Mer CLA180 c.c. 1595

Colour: A. Silver A/C: Insured / Std / NI / NA

Sp.Reading: 64872 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WDD1173422N 742242

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rtm / STD A/Rtm or

Tyre Size: F: \_\_\_\_\_

R: 275/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal. 5 mm

L/Bal. 5 mm

D.O.A. 12/11/22

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. 4 mm

L/Bal. 4 mm

D.O.I. 17/11/2022

Date / Time Action / Instruction

1 Est not ready

23/11 61Ry @ 3700 Cash

Date/Time, File Pass to?

: Prel. Report

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  : Site Insp (\$

: Interview (\$

: Tech Invs (\$

: Weekend (\$

Survey Fee:

Transportation:

\$ - RS. \$

Fuel \$

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$


# Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721  
 Mobile: 82636295 Email: thiamhenghuat@gmail.com

*Not Withheld*  
*11 Rmp & 3700k*  
*Penny Abu Rain*

Make/Model: MERCEDES BENZ CLA180  
 Engine/Chassis No.: WDD1173422N742242  
 Date of accident:  
 Damaged area: O/S Front

Date: 18/11/2022  
 Claim Type: TP  
 VRN: SJQ1164X



List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Front bumper	1	\$ 1,399.00	\$ 1,399.00
2	Front bumper side retainer	2	\$ 118.00	\$ 236.00
3	Front bumper bracket	2	\$ 99.00	\$ 198.00
4	Front bumper sensor holder o/s	2	\$ 23.00	\$ 46.00
5	Front fender cowling o/s	1	\$ 247.00	\$ 247.00
6	Front fender o/s	1	\$ 1,095.00	\$ 1,095.00
7	Headlamp support panel o/s	1	\$ 457.00	\$ 457.00
8	Headlamp module o/s	1	\$ 577.00	\$ 577.00
9	Headlamp o/s	1	\$ 3,236.00	\$ 3,236.00
10	Headlamp lower bracket o/s	1	\$ 105.00	\$ 105.00
11	Front shock absorber o/s <i>742</i>	1	\$ 837.00	\$ 837.00
12	Front shock absorber top mounting o/s	1	\$ 211.00	\$ 211.00
13	Front wheel knuckle o/s	1	\$ 547.00	\$ 547.00
14	Front wheel bearing o/s <i>285.60</i>	1	\$ 336.00	\$ 336.00
15	Front lower arm o/s <i>547.90</i>	1	\$ 612.00	\$ 612.00
16	Front endlink o/s	1	\$ 189.00	\$ 189.00
17	Front upper arm o/s	1	\$ 559.00	\$ 559.00
<b>Subtotal</b>				<b>\$ 10,887.00</b>
<b>List discount</b>				<b>10.00%</b>
<b>Total</b>				<b>\$ 9,798.30</b>

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Front bumper parking sensor o/s	2	\$ 342.00	\$ 684.00
2	Front bumper parking sensor harness o/s	1	\$ 279.00	\$ 279.00
3	Front fender cowling clips o/s	8	\$ 5.50	\$ 44.00
4	Front bumper clips	12	\$ 5.50	\$ 66.00
5	Front alloy wheel o/s	1	\$ 550.00	\$ 550.00
6	Front tyre o/s	1	\$ 280.00	\$ 280.00
7	Sundries	1	\$ 50.00	\$ 50.00
<b>Total</b>				<b>\$ 1,953.00</b>

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Repair Estimate

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portions. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	6	\$ 1,200.00
2	To disconnect front wire harness of electrical components to facilitate repairs, reconnect and check functions including focusing headlamps.	1	\$ 200.00
3	Supply spray paint material and necessary items to respray affected area / panel.	5	\$ 1,000.00
4	To remove and replace front o/s tyre & rim. To perform tyre balancing.	0.5	\$ 100.00
5	To remove and refit o/s front undercarriage for replacement of parts.	1	\$ 200.00
6	To conduct computerized wheel alignment.	0.75	\$ 150.00
7	To rust proof all affected portions after repair.	0.5	\$ 100.00
<b>Total labour</b>			<b>\$ 2,950.00</b>
<b>Estimate Grand Total</b>			<b>\$ 14,701.30</b>

3001  
201  
4001  
201  
1801  
601  
X

Date: \_\_\_\_\_  
 Signature: \_\_\_\_\_  
 Acknowledged by Repairer: \_\_\_\_\_  
 is subject to final approval from Insurance Company  
 • Supplementary item(s) must be resurveyed and  
 No illegal modification(s) is allowed  
 Third party survey is on a "Without Prejudice" basis  
 Parts prices are subject to confirmation  
 • To display damaged part(s) during resurvey  
 • To resurvey before/after spray painting  
 the Repairer of the following:  
 LKK Auto Consultants hence notify