

源 摩 哆 廠 GUAN MOTOR WORKS

Business Regn. No: 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

*Not Authorized
L1 Rep &
Recovery After Paint
3days*

REPAIR ESTIMATE GX491G

No.	Qty	List Items	
1	1	Front bumper	\$ <i>BR</i> 465.70 ✓
2	1	Front bumper LH fog lamp cover	\$ <i>M17</i> 56.00 ✓
3	1	Front bumper LH side reatiner	\$ <i>DIY</i> 46.70 ✓
4	1 set	Front bumper clips	\$ <i>na</i> 40.00 ✓
5	1	Front bumper inner reinforcement	\$ <i>R</i> 377.20 X
6	1	Front LH fender	\$ <i>BR</i> 420.30 ✓
7	1	Front LH fender under shield	\$ <i>SW</i> 187.50 X
8	1	LH headlamp rim/garnish	\$ <i>WR</i> 102.10 ✓
9	1	Front LH signal lamp	\$ <i>BR</i> 141.20 ✓
10	1	LH headlamp	\$ 301.40 ?
			\$ 2,138.10
Less 25%			\$ 534.53
Total :			\$ 1,603.58

<u>Labour</u>		
1	Labour Charges for remove/refit, panel beating, knocking and replacement of damages.	\$ 600.00 <i>400l</i>
2	To putty and spray Spray Paintings charges.	\$ 600.00 <i>200l</i>
3	To check wirings and lightings.	\$ 40.00 <i>20l</i>
4	To condut computerise wheel alignment test.	\$ <i>na</i> 80.00 X
5	To supply and apply anti rust treatment	\$ 60.00 <i>30l</i>
Total :		\$ 1,380.00

Total Parts and Labour : \$ 2,983.58

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: