

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CC3/AIG22011606/ANCE2**Date:** 01/03/2023**REFERENCE**

Insured/Claimant:	CHIN LI CHOONG	Policy No:	1900167067	
Date of Loss:	09/11/2022	Nature of Claim:	OD	Claim No: 7014519179SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGB7911G		
Make & Model:	AUDI A4, 2.0 SEDAN TFSI S-TRONIC (NAV) (A)	Engine No:	CVK082422
Reg. Date:	27/09/2019 (Man. Year: 2019)	Chassis No:	WAUZZZF4XKA076119
Colour:	Blue	Odometer:	40578 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$138,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,265.00	3,204.08	23,060.92	87.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,322.00	1,722.00	1,600.00	48.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,587.00	4,926.08	24,660.92	83.35
- Excess (S\$)	1,100.00	1,100.00	0.00	0.00
(S\$)	28,487.00	3,826.08	24,660.92	86.57
+ GST 8.00/8.00% (S\$)	2,278.96	306.09	1,972.87	86.57
Nett Amount (S\$)	30,765.96	4,132.17	26,633.79	86.57

INSPECTION

Date of Assignment:	18/11/2022		
Date Inspected:	16/11/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	2,377.00 FS	*1,901.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	612.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP -LH/RH	Not Necessary	79.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE -CENTER	Not Necessary	219.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT -LOWER CENTRE	Not Necessary	254.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE -LH/RH	N/s Damaged	144.00 FS	*57.20 FS
7	1		*RADIATOR GRILLE	Cracked	1,478.00 FS	*1,182.40 FS
8	2		*FRONT BUMPER AIR GUIDE GRILLE -LH /RH	Not Necessary	302.00 FS	*- FS
9	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	139.00 FS	*- FS
10	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	899.00 FS	*- FS
11	2		*FRONT BUMPER GUIDE SECTION -LH/RH	Not Necessary	82.00 FS	*- FS
12	1		*FRONT BUMPER TOP COVER	Not Necessary	143.00 FS	*- FS
13	1		*CAUTION SIGN STICKER	Not Necessary	16.00 FS	*- FS
14	1		*AIR CONDITIONER STICKER	Not Necessary	9.00 FS	*- FS
15	1		*FRONT BUMPER BRACKET	Not Necessary	154.00 FS	*- FS
16	2		*FRONT BUMPER SUPPORT -LH/RH	Not Necessary	64.00 FS	*- FS
17	2		*FRONT PARKING AID SENSOR -INNER /OUTER	Not Necessary	531.00 FS	*- FS
18	4		*FRONT PARKING AID SEAL RING	Not Necessary	10.00 FS	*- FS
19	1		*HORN HIGH TONE -LH	Not Necessary	134.00 FS	*- FS
20	1		*HORN LOW TONE -RH	Not Necessary	139.00 FS	*- FS
21	2		*HORN BRACKET -LH/RH	Not Necessary	66.00 FS	*- FS
22	2		*HEADLIGHT -LH/RH	Not Necessary	16,588.00 FS	*- FS
23	2		*LIFT CYLINDER -LH/RH	Not Necessary	462.00 FS	*- FS
24	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	107.00 FS	*- FS
25	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Not Necessary	21.00 FS	*- FS
26	2		*RADIATOR AIR GUIDE -LH/RH INNER	Not Necessary	64.00 FS	*- FS
27	2		*RADIATOR AIR GUIDE -LH/RH OUTER	Not Necessary	28.00 FS	*- FS
28	2		*RADIATOR AIR GUIDE -UPPER /LOWER	Not Necessary	44.00 FS	*- FS
29	1		*FRONT SIDE INSULATION	Not Necessary	640.00 FS	*- FS
30	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
31	1		*SUNDRIES	Necessary	400.00 FS	*2.88 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **26,265.00** **3,204.08**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR ,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	700.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND BOTH HEADLIGHT RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
4	TO RESPRAY FRONT BUMPER	New	900.00	550.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			3,322.00	1,722.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >