

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120**Our File No:** CC3/AIG22011607/AVCE2**Date:** 01/03/2023**REFERENCE**

Insured/Claimant:	MARJORY YEOH	Policy No:	2100473347-05	
Date of Loss:	11/11/2022	Nature of Claim:	OD	Claim No: 9667007337SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SLE429D</b>		
Make & Model:	AUDI S3, 2.0 TFSI Quattro (M)	Engine No:	CJX117973
Reg. Date:	04/07/2016 (Man. Year: 2016)	Chassis No:	WAUZZZ8V3G1098251
Colour:	Blue	Odometer:	55203 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$115,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	245/35 R19	Rear Tyre Size:	245/35 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,910.00	872.64	9,037.36	91.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,402.00	3,052.00	2,350.00	43.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>15,312.00</b>	<b>3,924.64</b>	<b>11,387.36</b>	<b>74.37</b>
<b>- Excess (S\$)</b>	2,000.00	2,000.00	0.00	0.00
<b>(S\$)</b>	13,312.00	1,924.64	11,387.36	85.54
<b>+ GST 8.00/8.00% (S\$)</b>	1,064.96	153.97	910.99	85.54
<b>Nett Amount (S\$)</b>	<b>14,376.96</b>	<b>2,078.61</b>	<b>12,298.35</b>	<b>85.54</b>

**INSPECTION**

Date of Assignment:	18/11/2022		
Date Inspected:	16/11/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

**Adjuster:** ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	3,359.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	195.00 FS	*- FS
3	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	43.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	196.00 FS	*- FS
5	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	1,054.00 FS	*- FS
6	1		*FRONT BUMPER END CAP - LH	Not Necessary	91.00 FS	*- FS
7	1		*FRONT FENDER - LH	Dented	954.00 FS	*763.20 FS
8	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	75.00 FS	*- FS
9	1		*FRONT FENDER BRACKET	Not Necessary	46.00 FS	*- FS
10	6		*FRONT FENDER RIVET	Necessary	23.00 FS	*18.24 FS
11	1		*FRONT FENDER BRACE	Bent	107.00 FS	*85.60 FS
12	1		*FRONT WHEEL HOUSING LINER - LH	Not Necessary	281.00 FS	*- FS
13	1		*HEADLIGHT GAS DISCHARGE LAMP - LH	Not Necessary	2,810.00 FS	*- FS
14	1		*FRONT PARKING AID SENSOR	Not Necessary	266.00 FS	*- FS
15	4		*FRONT PARKING AID SEAL RING	Not Necessary	10.00 FS	*- FS
16	1		*LHS FRONT RIM (NPA)	Not Necessary	0.00 FS	*- FS
17	1		*SUNDRIES	Necessary	400.00 FS	*5.60 FS
					<b>Total Parts (\$\$)</b>	<b>9,910.00 872.64</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,100.00	1,000.00
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	2,000.00	1,100.00
5	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,402.00</b>	<b>3,052.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >