

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS6/AIS22011609/SVY3E2**Date:** 27/02/2023**REFERENCE**

Insured/Claimant: ZHANG ZIQI Policy No: SP2001042337-01
Date of Loss: 15/11/2022 Nature of Claim: OD Claim No: 202222008187

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMJ2219S**
Make & Model: MAZDA 6, 2.0 SEDAN STANDARD 2WD (A) Engine No: PE21255441
Reg. Date: 26/02/2019 (Man. Year: 2018) Chassis No: JM6GL1072K0311815
Colour: Blue Odometer: 40035 km
Engine Capacity: 1998 cc
Market Value/New Car Price: S\$91,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R17 Rear Tyre Size: 225/55 R17
Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm
Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,228.30	4,405.50	822.80	15.74
Miscellaneous Items	35.00	0.00	35.00	100.00
Labour	1,610.00	1,340.00	270.00	16.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,873.30	5,745.50	1,127.80	16.41
- Excess (S\$)	0.00	600.00	-600.00	
(S\$)	6,873.30	5,145.50	1,727.80	25.14
+ GST 7.00/7.00% (S\$)	481.13	360.19	120.94	25.14
Nett Amount (S\$)	7,354.43	5,505.69	1,848.74	25.14

INSPECTION

Date of Assignment: 18/11/2022 Present Location: Cheng Hoe Motor Pte Ltd (Yishun)
Date Inspected: 18/11/2022 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
Estimated Period of Repair: 5.0 days Blk 1019 #01-374/382, Yishun Industrial Park A
Singapore 768761

Adjuster: S Mohamed Irfan Bin Mohamed Iqbal**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Feb 2023)
Parts:	143	MAZDA 6 2.0 SEDAN STANDARD 2WD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMJ2219S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 PC FRT BUMPER (WCP)	Broken	520.00 F	*520.00 F
2	1		*1 PC FRT BUMPER RH RETAINER (WCP)	Necessary	28.00 F	*28.00 F
3	1		*6 PCS FRT BUMPER CLIPS @2/PC (WCP)	Necessary	12.00 F	*18.00 F
4	1		*1 PC RH HEADLAMP (WCP)	Cracked	1,380.00 F	*1,380.00 F
5	1		*1 PC RH HEADLAMP LOWER BRACKET (WCP)	Dented	25.00 F	*25.00 F
6	1		*1 PC FRT GRILLE RH CHROME MOULDING (WCP)	Scratched	150.00 F	*160.00 F
7	1		*1 PC FRT RH FENDER (WCP)	Dented	160.00 F	*160.00 F
8	1		*1 PC FRT RH FENDER DUST COVER (WCP)	Dented	68.00 F	*68.00 F
9	1		*6 PCS FRT RH FENDER DUST COVER CLIPS @2/PC (WCP)	Necessary	12.00 F	*18.00 F
10	1		*1 PC FRT RH WHEEL RIM (WCP)	Scratched	550.00 F	*550.00 F
11	1		*1 PC FRT RH LOWER ARM (WCP)	Dented	230.00 F	*230.00 F
12	1		*1 PC FRT RH KNUCKLE (WCP)	Dented	185.00 F	*185.00 F
13	1		*1 PC FRT RH ABSORBER STRUT (WCP)	Dented	170.00 F	*170.00 F
14	1		*1 PC FRT RH ABSORBER STRUT TOP MOUNTING (WCP)	Not Necessary	55.00 F	*- F
15	1		*1 PC FRT RH ABSORBER STRUT TOP BEARING (WCP)	Not Necessary	48.00 F	*- F
16	1		*1 PC FRT RH STABILIZER LINK (WCP)	Dented	45.00 F	*48.00 F
17	1		*2 PCS FRT RH STABILIZER BAR BUSHES @35/PC (WCP)	Not Necessary	70.00 F	*- F
18	1		*1 PC FRT RH DRIVE SHAFT (WCP)	Not Necessary	600.00 F	*- F
19	1		*1 PC FRT RH WHEEL HUB (WCP)	Dented	250.00 F	*250.00 F
20	1		*1 PC STEERING TIE ROD RH (WCP)	Dented	65.00 F	*65.00 F
21	1		*1 PC STEERING TIE ROD END RH (WCP)	Dented	60.00 F	*60.00 F
Supplementary #1						
22	1		*1 PC WIPER TANK (WCP)	Bent	70.00 F	*70.00 F

F=Franchise part.

Sub Total (\$)	4,753.00	4,005.00
+ Margin on L,N Items 10.00/10.00% (\$)	475.30	400.50

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	5,228.30
						4,405.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	1 UNIT AUTO TRANSMISSION OIL (NOT NECESSARY)	35.00	0.00
Sub Total (\$\$)			35.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING (BY INSURANCE)	New	0.00	0.00
2	REMOVE & REPLACE FRT BUMPER,FENDER,HEADLAMPS, & ATTACHMENTS,PANEL BEAT & REPAIR RH FENDER APRON,INNER BRACKETS,HEADLAMP TOP SUPPORT PANEL & REPLACE DAMAGED BODY PARTS	New	600.00	500.00
3	REMOVE & REFIX FRT SUSPENSION / UNDERCARRIAGE AND CHECK STEERING	New	250.00	180.00
4	RESET WHEEL ALIGNMENT	New	80.00	60.00
5	PUTTY & RESPRAY PAINT ON FRT BUMPER,FRT RH FENDER,FRT TOP PANEL,FRT RH INNER MEMBER	New	680.00	600.00
Gross Labour Cost (\$\$)			1,610.00	1,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >