

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22011611/AVCM4**Date:** 01/03/2023**REFERENCE**

Insured/Claimant: LAU SHEN YI SARAH (LIU RUIYI SARAH)

Policy No: 2070111574

Date of Loss: 10/10/2022

Nature of Claim: OD Claim No: 9270450061SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKS8399S**

Make & Model: AUDI Q2, 999cc 1.0 TFSI S TRONIC (A)

Engine No: CHZC33524

Reg. Date: 30/07/2020 (Man. Year: 2019)

Chassis No: WAUZZZGA7KA084781

Colour: White

Odometer: 12508 km

Engine Capacity: 999 cc

Market Value/New Car Price: S\$128,000.00

Price:

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,595.00	730.40	6,864.60	90.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,432.00	3,452.00	4,980.00	59.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,027.00	4,182.40	11,844.60	73.90
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	15,227.00	3,382.40	11,844.60	77.79
+ GST 8.00/8.00% (S\$)	1,218.16	270.59	947.57	77.79
Nett Amount (S\$)	16,445.16	3,652.99	12,792.17	77.79

INSPECTION

Date of Assignment: 21/11/2022

Date Inspected: 17/11/2022 Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR - LH	Repair	2,962.00 FS	*- FS
2	1		*REAR OUTER DOOR SEAL - LH	Not Necessary	151.00 FS	*- FS
3	1		*BONDING AGENT	Not Necessary	51.00 FS	*- FS
4	1		*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS
5	1		*APPLICATOR	Not Necessary	9.00 FS	*- FS
6	1		*REAR DOOR CATCH - LH	Not Necessary	134.00 FS	*- FS
7	1		*REAR OUTER DOOR SEAL - LH	Not Necessary	66.00 FS	*- FS
8	1		*REAR DOOR COVER - LH	Cut	238.00 FS	*190.40 FS
9	1		*REAR DOOR SIDE MEMBER TRIM - LH	Not Necessary	251.00 FS	*- FS
10	1		*REAR WHEEL HOUSING LINER - LH	Not Necessary	220.00 FS	*- FS
11	1		*REAR ALUMINIUM RIM	Not Necessary	1,002.00 FS	*- FS
12	1		*REAR ALUMINIUM RIM RUBBER VALVE	Not Necessary	4.00 FS	*- FS
13	1		*REAR BUMPER	Repair	1,363.00 FS	*- FS
14	1		*REAR BUMPER SPOILER	Cut	316.00 FS	*252.80 FS
15	1		*REAR BUMPER REFLECTOR - LH	Not Necessary	34.00 FS	*- FS
16	1		*REAR BUMPER GUIDE SECTION - LH	Not Necessary	60.00 FS	*- FS
17	2		*REAR WHEEL COVER - LH / RH	N/s Cut / O/s Necessary	360.00 FS	*287.20 FS
18	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	7,595.00 730.40
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID	New	280.00	280.00
2	TO REMOVE AND TRANSFER LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	400.00	0.00
3	TO DISMANTLE AND RENEW REAR BUMPER AND LHS REAR DOOR. TO REPAIR LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,800.00	500.00
4	TO RESPRAY REAR BUMPER, LHS REAR FENDER AND LHS REAR DOOR	New	3,000.00	1,650.00
5	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
7	TO DISMANTLE FRONT LHS WING MIRROR MOUNTING TO FACILITATE RESPRAY OF FRONT LHS DOOR (Supplementary)	New	280.00	280.00
8	TO RESPRAY LHS FRONT DOOR (Supplementary)	New	1,200.00	550.00
Gross Labour Cost (S\$)			8,432.00	3,452.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >