5/25/23, 2:08 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG22011612/AGVY3M4

25/05/2023 Date:

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No:

1001922844

Claimant Vehicle SLW5889G No:

Insured Vehicle No: FBP2031P

Date of Loss: 01/11/2022 Nature of Claim: TP Claim No: 291265

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLW5889G

VOLKSWAGEN PASSAT, 2.0 (A) Make & Model: Engine No:

Reg. Date: 01/01/2018 (Man. Year: 2018) Chassis No: WVWZZZ3CZJE099220

Colour: Odometer: 62201 km Silver

Engine Capacity: 1984 cc Market Value/New Car

N/A Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/35R19 235/35R19 Rear Tyre Size: Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		1,404.00	867.60	536.40	38.21
Miscellaneous Items		0.00	0.00	0.00	
Labour		450.00	230.00	220.00	48.89
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	1,854.00	1,097.60	756.40	40.80
	Approved Total (Overridden) (S\$)		800.00		
	Nett Amount (S\$)	1,854.00	800.00	1,054.00	56.85

INSPECTION

Date of Assignment: 18/11/2022

> ADVANCE AUTO GARAGE 23 KAKI BUKIT AVENUE 4,

21/11/2022 Inspected At: #04-01 VICOM KAKI BUKIT INSPECTION Date Inspected:

CENTER,

SINGAPORE 415933.

Estimated Period of Repair: 1.0 days

XING GUO QIANG Adjuster: Manager: **VERON CHEN**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 May 2023)

Parts: 143 VOLKSWAGEN PASSAT 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLW5889G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR WING MIRROR	Damaged	859.00 FL	*859.00 FL
2	1		*FRONT DOOR WING MIRROR COVER	Cracked	105.00 FL	*105.00 FL
3	1		*FRONT DOOR WING MIRROR GLASS	Not Necessary	398.00 FL	*- FL
4	1		*FRONT DOOR WING MIRROR SIGNAL LAMP	Not Necessary	198.00 FL	*- FL
F=Fra	anchise	part. L=ListIte	emDisc.	Sub Total (S\$)	1,560.00	964.00
			- List Item Discount on L I	tems 10.00/10.00% (S\$)	156.00	96.40
				Total Parts (S\$)	1,404.00	867.60
			Report was unsubmitted during th	is print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	PANEL BEATING, REMOVE AND REFIT PARTS	New	200.00	100.00
2	SPRAY PAINTING TO AFFECTED AREA	New	200.00	100.00
3	WIRING CHECK	New	50.00	30.00
		Gross Labour Cost (S\$)	450.00	230.00
	Report was unsu	ubmitted during this print-out.		

< END OF ESTIMATES >