

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/ICS22011614/AVY3M4**Date:** 09/02/2023**REFERENCE**

Handling Insurer: ECICS Limited Policy No:

**Claimant Vehicle No :** SLB7630H **Insured Vehicle No :** SMM3632J

Date of Loss: 16/11/2022 Nature of Claim: TP Claim No: DMPC2200562H/02/CT

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SLB7630H**

Make & Model: TOYOTA SIENTA, 1.5 G (A) Engine No: 1NZC967324

Reg. Date: 22/09/2008 (Man. Year: 2008) Chassis No: NCP815054279

Colour: Bronze Odometer: 130908 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 195/55 R15 Rear Tyre Size: 195/55 R15

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,798.90	6,893.27	1,905.63	21.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,680.00	2,970.00	1,710.00	36.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>13,478.90</b>	<b>9,863.27</b>	<b>3,615.63</b>	<b>26.82</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>7,800.00</b>		
<b>Nett Amount (S\$)</b>	<b>13,478.90</b>	<b>7,800.00</b>	<b>5,678.90</b>	<b>42.13</b>

**INSPECTION**

Date of Assignment: 17/11/2022

Date Inspected: 18/11/2022 Inspected At: 25 KAKI BUKIT ROAD 4,  
#05-36/37, SYNERGY @ KB, SINGAPORE  
417800  
REPAIRER: AKA AUTO PTE LTD

Estimated Period of Repair: 9.0 days

**Adjuster:** ADRIAN LING**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Feb 2023)
Parts:	M1-MPV	TOYOTA SIENTA 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLB7630H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH DOOR	Dented	1,158.40 FL	*1,158.40 FL
2	1		*FRONT LH DOOR LOCK	Not Necessary	302.40 FL	*- FL
3	1		*FRONT LH DOOR WEATHERSTRIPE	Not Necessary	284.90 FL	*- FL
4	1		*FRONT LH DOOR INNER TRIM BOARD	Not Necessary	568.40 FL	*- FL
5	1		*SLIDING DOOR LH	Dented	1,298.50 FL	*1,298.50 FL
6	1		*SLIDING DOOR LOCK LH	Damaged	343.10 FL	*343.10 FL
7	1		*SLIDING DOOR WEATHERSTRIPE LH	Not Necessary	268.30 FL	*- FL
8	1		*SLIDING DOOR GLASS REGULATOR GEAR	Damaged	261.40 FL	*261.40 FL
9	1		*SLIDING DOOR GLASS REGULATOR MOTOR	Not Necessary	368.60 FL	*- FL
10	1		*REAR LH FENDER	Distorted	1,098.40 FL	*1,098.40 FL
11	1		*REAR BUMPER	Deformed	830.80 FL	*830.80 FL
12	1		*REAR BUMPER SIDE HOLDER LH	Necessary	45.90 FL	*45.90 FL
13	1		*REAR AXLE	Bent	1,712.90 FL	*1,712.90 FL
14	1		*REAR LH WHEEL HUB C/W BEARING	Damaged	545.90 FL	*545.90 FL
15	1		*REAR LH SHOCK ABSORBER	Not Necessary	294.90 FL	*- FL
16	1		*SLIDING DOOR INNER TRIM BOARD	Cracked	602.40 FL	*602.40 FL
17	1		*SET FRONT LH DOOR INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
18	1		*SET SLIDING DOOR INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
19	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
20	1		*REAR LH WHEEL RIM	Cut	880.00 FS	*680.00 FS
21	1		*REAR LH TYRE	Deformed	280.00 FS	*200.00 FS
					Sub Total (\$\$)	11,295.20 8,867.70
					- List Item Discount on L Items 25.00/25.00% (\$\$)	2,496.30 1,974.43
					Total Parts (\$\$)	8,798.90 6,893.27

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	1,800.00	1,100.00
2	SPRAY PAINTING	New	1,400.00	1,000.00
3	WIRING	New	100.00	30.00
4	TO SPRAY TUFF COAT	New	150.00	80.00
5	TO REMOVE REVERSE SENSOR	New	100.00	50.00
6	TO TRANSFER FRONT DOOR FITTINGS	New	150.00	80.00
7	TO TRANSFER SLIDING DOOR FITTINGS	New	150.00	80.00
8	TO REMOVE UPHOLSTERY	New	150.00	60.00
9	TO REMOVE FUEL TANK	New	150.00	60.00
10	TO REMOVE REAR UNDERCARRIAGE	New	380.00	350.00
11	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
<b>Gross Labour Cost (S\$)</b>			<b>4,680.00</b>	<b>2,970.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >