

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22011615/KPA3Q2**Date:** 13/03/2023**REFERENCE**

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP0001039188
Claimant Vehicle No :	SKB5689P	Insured Vehicle No :	XD8504E
Date of Loss:	12/11/2022	Nature of Claim:	TP
		Claim No:	202222008116

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKB5689P	Engine No:	1ZRX099443
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053REE104118144
Reg. Date:	13/06/2011 (Man. Year: 2011)	Odometer:	56759 km
Colour:	Metallic Gold		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,343.84	838.50	4,505.34	84.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,400.00	1,680.00	720.00	30.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,743.84	2,518.50	5,225.34	67.48
Approved Total (Overridden) (S\$)		2,000.00		
Nett Amount (S\$)	7,743.84	2,000.00	5,743.84	74.17
+ Loss of Use (6.0 x S\$50.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,307.45		

INSPECTION

Date of Assignment:	18/11/2022	Caris Autoworks Pte Ltd - SIN MING (HQ)
Date Inspected:	18/11/2022 Inspected At:	160 SIN MING DR #05-03 SIN MING AUTOCITY
Estimated Period of Repair:	6.0 days	Singapore 575722

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Mar 2023)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKB5689P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER (FRONT)	Repair	535.80 FL	*- FL
2	1		*BUMPER (REAR)	Dented / Cut	585.10 FL	*585.10 FL
3	1		*MANGUARD (FRONT LEFT)	Repair	499.20 FL	*- FL
4	1		*MANGUARD (REAR LEFT)	Repair	1,217.80 FL	*- FL
5	1		*TYRE (REAR LEFT) (60%)	Punctured	134.40 FS	*100.80 FS
6	1		*TYRE RIM (REAR LEFT)	Dented	398.50 FL	*398.50 FL
7	1		*WHEEL KNUCKLE (REAR LEFT)	Serviceable	968.40 FL	*- FL
8	1		*LOWER ARM (REAR LEFT)	Serviceable	630.60 FL	*- FL
9	1		*LOWER UPPER ARM (REAR LEFT)	Serviceable	556.40 FL	*- FL
10	1		*WHEEL BEARING (REAR LEFT)	Serviceable	789.10 FL	*- FL
11	1		*S/ABSORBER (REAR LEFT)	Serviceable	230.90 FL	*- FL
12	1		*BODY CLIPS	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,626.20	1,084.40
- List Item Discount on L Items 20.00/25.00% (S\$)	1,282.36	245.90
Total Parts (S\$)	5,343.84	838.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL KNOCKING	New	800.00	600.00
2	SPRAY PAINTING	New	1,200.00	1,000.00
3	WHEEL ALIGNMENT	New	80.00	60.00
4	WIRE CHECKING & DIAGNOSTIC	New	60.00	20.00
5	LABOUR CHARGE TO CHARGE WHEEL ARMS	New	260.00	0.00
Gross Labour Cost (\$\$)			2,400.00	1,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >