

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22011616/ANP3Q2**Date:** 20/04/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00237752101
Claimant Vehicle No :	YQ6972U	Insured Vehicle No :	SGX8233H
Date of Loss:	16/11/2022	Nature of Claim:	TP
		Claim No:	SNM22D208260/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YQ6972U	Engine No:	1GD8913299
Make & Model:	TOYOTA DYNA 150, 3.0 D (M)	Chassis No:	JHHAGV4610K002546
Reg. Date:	27/05/2022 (Man. Year: 2022)	Odometer:	11315 km
Colour:	Silver		
Engine Capacity:	2755 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/75 R15	Rear Tyre Size:	145/80 R13
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,916.80	4,015.12	2,901.68	41.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,400.00	1,010.00	390.00	27.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,316.80	5,025.12	3,291.68	39.58
Approved Total (Overridden) (S\$)		4,000.00		
Nett Amount (S\$)	8,316.80	4,000.00	4,316.80	51.90

INSPECTION

Date of Assignment:	17/11/2022		1 KAKI BUKIT AVE 6
Date Inspected:	18/11/2022	Inspected At:	#01-27/01-45 SINGAPORE 417883 Repairer:Fong Motors (HQ)
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 19 Apr 2023)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YQ6972U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH DOOR	Dented	1,941.80 F	*1,480.00 FL
2	1		*RH DOOR OUTER HANDLE	Cut	241.00 F	*241.00 FL
3	1		*RH HEAD LAMP	Cut	1,272.30 F	*1,272.30 FL
4	1		*FRONT BUMPER	Deformed	784.90 F	*784.90 FL
5	1		*CORNER PANEL	Repair	526.40 F	*- FL
6	1		*STEP GARNISH	Cut	327.70 F	*327.70 FL
7	1		*DOOR BOARD	Cracked	531.70 F	*531.70 FL
8	1		*RH DOOR GLASS REGULATOR	Not Necessary	385.10 F	*- FL
9	1		*RH DOOR OUTER RUBBER	Cut	123.20 F	*123.20 FL
10	1		*SIDE MIRROR	Damaged	352.70 F	*352.70 FL
11	1		*SET BUMPER CLIP	Not Necessary	50.00 FS	*- FS
12	1		*STICKER	Necessary	380.00 FS	*180.00 FS
					Sub Total (\$\$)	6,916.80 5,293.50
					- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00 1,278.38
					Total Parts (\$\$)	6,916.80 4,015.12

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHARGE DOOR AND COMPARTMENTS	New	120.00	80.00
2	TO KNOCK AND CHARGE PARTS	New	600.00	400.00
3	TO CONDUCT WIRING CHECKS	New	80.00	30.00
4	SPRAY PAINTING ON ALL AFFECTED PARTS	New	600.00	500.00
Gross Labour Cost (\$\$)			1,400.00	1,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >