

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard, #04-01 Suntec Tower Three  
Singapore 038988**Our File No:** CS/EGI22011618/TQY3E2**Date:** 10/01/2023**REFERENCE**

Insured/Claimant:	IBMS TECHNOLOGY PTE LTD	Policy No:	DMCG22005254
Date of Loss:	15/11/2022	Nature of Claim:	OD
		Claim No:	CDMCG22002467

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>GBJ4415J</b>	Engine No:	K9KE628D646003
Make & Model:	NISSAN NV200 ACENTA, 1.5 CDI (M)	Chassis No:	VSKYBAM20U0175431
Reg. Date:	26/04/2019 (Man. Year: 2018)	Odometer:	100961 km
Colour:	White		
Engine Capacity:	1461 cc		
Market Value/New Car Price:	S\$55,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	12,968.46	6,070.52	6,897.94	53.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,180.00	1,570.00	1,610.00	50.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>16,148.46</b>	<b>7,640.52</b>	<b>8,507.94</b>	<b>52.69</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,100.00</b>		
<b>- Excess (S\$)</b>	800.00	800.00	0.00	0.00
<b>Nett Amount (S\$)</b>	<b>15,348.46</b>	<b>5,300.00</b>	<b>10,048.46</b>	<b>65.47</b>

**INSPECTION**

Date of Assignment: 17/11/2022

Date Inspected: 18/11/2022 Inspected At:

Lkt Group Pte Ltd (HQ)  
Blk 3006 Ubi Road 1, #01 - 384 Kampong Ubi Industrial Estate  
Singapore 408700

Estimated Period of Repair: 6.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

Reference	
<b>Part Source:</b>	(Last Synchronised: 10 Jan 2023)
<b>Parts:</b>	N/A NISSAN NV200 ACENTA 1.5 CDI (M) (Model not available in database)
<b>Labour:</b>	Repairer's (Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBJ4415J)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET (NPA)	Repair	0.00 FL	*- FL
2	1		*FRONT FENDER RH (NPA)	Repair	0.00 FL	*- FL
3	1		*FRONT FENDER INNER PANEL RH	Repair	442.00 FL	*- FL
4	1		*FRONT FENDER INNER SHIELD RH	Not Necessary	182.00 FL	*- FL
5	1		*HEADLAMP RH	Cracked	759.60 FL	*424.90 FL
6	1		*FRONT BUMPER	Deformed	740.50 FL	*636.70 FL
7	1		*FRONT BUMPER SIDE RETAINER	O/S Deformed/N/S Not Necessary	97.20 FL	*48.60 FL
8	1		*FRONT BUMPER BRACKET	O/S Deformed/N/S Not Necessary	183.40 FL	*91.70 FL
9	1		*FRONT BUMPER TOP SIDE GARNISH RH	Missing	448.60 FL	*329.80 FL
10	1		*FRONT BUMPER SPONGE	Deformed	180.00 FL	*180.00 FL
11	1		*FRONT BUMPER REINFORCEMENT	Bent	296.00 FL	*296.00 FL
12	1		*FRONT BUMPER REINFORCEMENT BRACKET	O/S Bent / N/S Not Necessary	251.20 FL	*125.60 FL
13	1		*FRONT BUMPER FOG LAMP RH	Not Necessary	268.20 FL	*- FL
14	1		*FRONT GRILLE	Cracked	287.40 FL	*287.40 FL
15	1		*FRONT GRILLE LOGO	Necessary	72.40 FL	*72.40 FL
16	1		*FRONT GRILLE LOWER GARNISH	Cut	198.70 FL	*198.70 FL
17	1		*WIPER WASHER TANK	Cracked	215.00 FL	*215.00 FL
18	1		*WIPER WASHER TANK MOTOR	Not Necessary	171.00 FL	*- FL
19	1		*FRONT CHASSIS MEMBER RH	Repair	726.00 FL	*- FL
20	1		*FRONT SUPPORT TOP PANEL	Bent	658.70 FL	*300.00 FL
21	1		*FRONT SUPPORT PANEL FRAME ASSY	Bent	722.80 FL	*535.00 FL
22	1		*FRONT SUPPORT SIDE AIR-GUIDE	O/S Deformed/N/S Not Necessary	252.20 FL	*126.10 FL
23	1		*FRONT AIR-DUCT	Cracked	125.60 FL	*125.60 FL
24	1		*RADIATOR ASSY	Cracked	1,045.00 FL	*893.70 FL
25	1		*RADIATOR FAN ASSY	Not Necessary	986.70 FL	*- FL
26	2		*RADIATOR TOP BRACKET	Not Necessary	144.00 FL	*- FL
27	1		*RADIATOR TOP HOSE	Not Necessary	95.00 FL	*- FL
28	1		*RADIATOR BOTTOM HOSE	Not Necessary	109.52 FL	*- FL
29	1		*A/C CONDENSER	Not Necessary	1,128.40 FL	*- FL
30	1		*A/C CONDENSER HIGH PRESSURE PIPE	Bent	255.60 FL	*255.60 FL
31	1		*A/C CONDENSER LOW PRESSURE PIPE	Bent	110.00 FL	*110.00 FL
32	1		*A/C CONDENSER SUCTION PIPE	Not Necessary	195.00 FL	*- FL
33	1		*A/C CONDENSER DISCHARGE HOSE	Not Necessary	248.35 FL	*- FL
34	1		*INTERCOOLER	Bent	1,270.00 FL	*1,270.00 FL
35	1		*INTERCOOLER INLET PIPE	Not Necessary	261.00 FL	*- FL
36	1		*INTERCOOLER OUTLET PIPE	Not Necessary	249.00 FL	*- FL
37	1		*SUNDRIES	Not Necessary	60.00 FS	*- FS
38	1		*A/C COMPRESSOR FLUID	Not Necessary	80.00 FS	*- FS
39	1		*RADIATOR COOLANT	Necessary	130.00 FS	*60.00 FS
40	1		*SET FRONT BONNET STICKER	Not Necessary	110.00 FS	*- FS
41	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
42	1		*SET FRONT GRILLE CLIPS	Necessary	100.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*HEADLAMP PANEL SEALANT RH	Not Necessary	70.00 FS	*- FS
44	1		*FRONT FENDER INNER PANEL SEALANT RH	Not Necessary	90.00 FS	*- FS
45	1		*FRONT SUPPORT TOP PANEL SEALANT	Necessary	90.00 FS	*40.00 FS
46	1		*FRONT SUPPORT PANEL ASSY SEALANT	Necessary	120.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>14,306.07</b>	<b>6,722.80</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	1,337.61	652.28
<b>Total Parts (\$)</b>	<b>12,968.46</b>	<b>6,070.52</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING AND STRENGTHEN PARTS ON ACCIDENT AREA	New	1,400.00	700.00
2	CHECK WIRING SYSTEM AFTER DISCONNECT AND CONNECT	New	80.00	30.00
3	TO R&R A/C CONDENSER AND CONFIRM A/C TEMPERATURE	New	150.00	100.00
4	TO R&R RADIATOR AND PERFORM PRESSURE / COOLING TEST	New	150.00	100.00
5	TO APPLY UNDERCOATING FOR RUST ROOFING	New	200.00	40.00
6	SPRAY PAINTING ON ACCIDENT AREA	New	1,200.00	600.00
			<b>Gross Labour Cost (\$)</b>	<b>3,180.00</b>
				<b>1,570.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >