

LKT GROUP PTE LTD

BLK 3006 UBI ROAD 1

#01-384 SINGAPORE 408700

OFFICE NO. : 6846 6260 / FAX NO. : 6477 9002

E-MAIL : lkt.mabel@gmail.com / claims.lkt@gmail.com

Date : 16-Nov-22

Registration no. : GBJ4415J / NISSAN NV200 ACENTA DCI 1.5 M / 2019

DOA : 15-Nov-22

Estimate No. : LKT007_GBJ4415J_NV200

S/N	Qty	Item	Amount
<u>LIST ITEMS</u>			
1	1	Bonnet	To Repair 0.00 <i>Ry</i>
2	1	Front fender RH	To Repair 0.00 <i>Ry</i>
3	1	Front fender inner panel RH	442.00 <i>Rx</i>
4	1	Front fender inner shield RH	182.00 <i>X nn</i>
5	1	Headlamp RH	759.60 <i>Can</i> 424.90
6	1	Front bumper	740.50 <i>de</i> 636.70
7	2	Front bumper side retainer x2	<i>LHx nn</i> 97.20 <i>RH-de</i> 48.60
8	2	Front bumper bracket x2	<i>LHx nn</i> 183.40 <i>RH-de</i> 91.70
9	1	Front bumper top side garnish RH	448.60 <i>mis</i> 329.80
10	1	Front bumper sponge	180.00 <i>de</i>
11	1	Front bumper reinforcement	296.00 <i>bt</i>
12	2	Front bumper reinforcement bracket x2	<i>LH-X</i> 251.20 <i>RHbt</i> 125.60
13	1	Front bumper fog lamp RH	268.20 <i>X nn</i>
14	1	Front grille	287.40 <i>Can</i>
15	1	Front grille logo	72.40 <i>de</i>
16	1	Front grille lower garnish	198.70 <i>cut</i>
17	1	Wiper washer tank	215.00 <i>Can</i>
18	1	Wiper washer tank motor	171.00 <i>X nn</i>
19	1	Front chassis member RH	726.00 <i>Ry</i>
20	1	Front support top panel	658.70 <i>bt</i> 300
21	1	Front support panel frame assy	722.80 <i>bt</i> 535
22	2	Front support side air-guide x2	<i>LH-X nn</i> 252.20 <i>RH de</i> 126.10
23	1	Front air-duct	125.60 <i>Can</i>
24	1	Radiator assy	1045.00 <i>Can</i> 893.70
25	1	Radiator fan assy	986.70 <i>X nn</i>
26	2	Radiator top bracket x2	144.00 <i>X nn</i>
27	1	Radiator top hose	95.00 <i>X nn</i>
28	1	Radiator bottom hose	109.52 <i>X nn</i>
29	1	A/C condenser	1128.40 <i>X nn</i>
30	1	A/C condenser high pressure pipe	255.60 <i>bt</i>
31	1	A/C condenser low pressure pipe	110.00 <i>bt</i>
32	1	A/C condenser suction hose	195.00 <i>X nn</i>
33	1	A/C condenser discharge hose	248.35 <i>X nn</i>
34	1	Intercooler	1270.00 <i>bt</i>
35	1	Intercooler inlet pipe	261.00 <i>X nn</i>
36	1	Intercooler outlet pipe	249.00 <i>X nn</i>
			13376.07
			6522.80
			5870.52
Less 10%			3344.02
			10032.05

LKT GROUP PTE LTD

BLK 3006 UBI ROAD 1
 #01-384 SINGAPORE 408700
 OFFICE NO. : 6846 6260 / FAX NO. : 6477 9002
 E-MAIL : lkt.mabel@gmail.com / claims.lkt@gmail.com

Date : 16-Nov-22

Registration no. : GBJ4415J / NISSAN NV200 ACENTA DCI 1.5 M / 2019

DOA : 15-Nov-22 Estimate No. : LKT007_GBJ4415J_NV200

S/N	Qty	Item	Amount
<u>SPECIAL NETT ITEMS</u>			
1	1	Sundries	60.00 X NY
2	1	A/C compressor fluid	80.00 X NY
3	1	Radiator coolant	130.00 960 New
4	1set	Front bonnet sticker	110.00 X NY
5	1set	Front bumper clips	80.00 30 New
6	1set	Front grille clips	100.00 30 New
7	1	Headlamp panel sealant RH	70.00 X NY
8	1	Front fender inner panel sealant RH	90.00 X NY
9	1	Front support top panel sealant	90.00 40 New
10	1	Front support panel assy sealant	120.00 40 New
			930.00
Parts Total			10962.05

<u>LABOUR & MISC CHARGES</u>			
1	1	Panel beating and strenghten parts on accident area.	1400.00 700
2	1	Check wiring system after disconnect and connect.	80.00 30
3	1	To R&R a/c condenser and confirm a/c temperature.	150.00 100? ✓
4	1	To R&R radiator and perform pressure/cooling test.	150.00 100? ✓
5	1	To apply undercoating for rust roofing.	200.00 40
6	1	Spray painting on accident area.	1200.00 600
Labour Total			1570 3180.00

Total Parts and Labour Cost of Repair 14142.05

5870.52
 200
 1570
 20% Lump sum
 COR (L/S)

Pre-Repair Survey :-
 Name : Taufik
 Contact no. : 97495749 / 62563561
 Date / Time : 12/11/22 @ 11:40am
 Not Authorise
 Ex: to be advise
 4/5 Body after repair
 6 days
 Taufik@lkt.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: