

# LKT GROUP PTE LTD

BLK 3006 UBI ROAD 1

#01-384 SINGAPORE 408700

OFFICE NO. : 6846 6260 / FAX NO. : 6477 9002

E-MAIL : lkt.mabel@gmail.com / claims.lkt@gmail.com

Date : 16-Nov-22

Registration no. : GBJ4415J / NISSAN NV200 ACENTA DCI 1.5 M / 2019

DOA : 15-Nov-22 Estimate No. : LKT007\_GBJ4415J\_NV200

S/N	Qty	Item	Amount
<u>LIST ITEMS</u>			
1	1	Bonnet	To Repair 0.00
2	1	Front fender RH	To Repair 0.00
3	1	Front fender inner panel RH	442.00
4	1	Front fender inner shield RH	182.00
5	1	Headlamp RH	759.60
6	1	Front bumper	740.50
7	2	Front bumper side retainer x2	97.20
8	2	Front bumper bracket x2	183.40
9	1	Front bumper top side garnish RH	448.60
10	1	Front bumper sponge	180.00
11	1	Front bumper reinforcement	296.00
12	2	Front bumper reinforcement bracket x2	251.20
13	1	Front bumper fog lamp RH	268.20
14	1	Front grille	287.40
15	1	Front grille logo	72.40
16	1	Front grille lower garnish	198.70
17	1	Wiper washer tank	215.00
18	1	Wiper washer tank motor	171.00
19	1	Front chassis member RH	726.00
20	1	Front support top panel	658.70
21	1	Front support panel frame assy	722.80
22	2	Front support side air-guide x2	252.20
23	1	Front air-duct	125.60
24	1	Radiator assy	198.70
25	1	Radiator fan assy	986.70
26	1	A/C condenser	1128.40
27	1	A/C condenser high pressure pipe	255.60
28	1	A/C condenser low pressure pipe	110.00
29	1	A/C condenser suction hose	195.00
30	1	A/C condenser discharge hose	248.35
31	1	Intercooler	1270.00
32	1	Intercooler inlet pipe	261.00
33	1	Intercooler outlet pipe	249.00
			12181.25
Less 10%			3045.31
			9135.94

# LKT GROUP PTE LTD

BLK 3006 UBI ROAD 1

#01-384 SINGAPORE 408700

OFFICE NO. : 6846 6260 / FAX NO. : 6477 9002

E-MAIL : lkt.mabel@gmail.com / claims.lkt@gmail.com

Date : 16-Nov-22

Registration no. : GBJ4415J / NISSAN NV200 ACENTA DCI 1.5 M / 2019

DOA : 15-Nov-22 Estimate No. : LKT007\_GBJ4415J\_NV200

S/N	Qty	Item	Amount
<u>SPECIAL NETT ITEMS</u>			
1	1	Sundries	60.00
2	1	A/C compressor fluid	80.00
3	1	Radiator coolant	130.00
4	1set	Front bonnet sticker	110.00
5	1set	Front bumper clips	80.00
6	1set	Front grille clips	100.00
7	1	Headlamp panel sealant RH	70.00
8	1	Front fender inner panel sealant RH	90.00
9	1	Front support top panel sealant	90.00
10	1	Front support panel assy sealant	120.00
			<hr/>
			930.00
			<hr/>
<b>Parts Total</b>			<b>10065.94</b>
<hr/>			
<u>LABOUR &amp; MISC CHARGES</u>			
1	1	Panel beating and strenghten parts on accident area.	1400.00
2	1	Check wiring system after disconnect and connect.	80.00
3	1	To R&R a/c condenser and confirm a/c temperature.	150.00
4	1	To R&R radiator and perform pressure/cooling test.	150.00
5	1	To apply undercoating for rust roofing.	200.00
6	1	Spray painting on accident area.	1200.00
			<hr/>
<b>Labour Total</b>			<b>3180.00</b>
<hr/>			
<b>Total Parts and Labour Cost of Repair</b>			<b>13245.94</b>
<hr/>			

20% Lump sum  
COR (L/S)

Pre-Repair Survey :-

Name : \_\_\_\_\_

Contact no. : \_\_\_\_\_

Date / Time : \_\_\_\_\_