

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22011619/GPA3Q2**Date:** 30/03/2023**REFERENCE**

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP0001054424
Claimant Vehicle No :	SJD8362M	Insured Vehicle No :	SMQ5658B
Date of Loss:	16/11/2022	Nature of Claim:	TP
		Claim No:	202222008203

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJD8362M	Engine No:	L13A4046811
Make & Model:	HONDA FIT, 1.3 G (A)	Chassis No:	GE61041831
Reg. Date:	04/04/2008 (Man. Year: 2008)	Odometer:	482350 km
Colour:	Blue		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,206.84	3,687.96	2,518.88	40.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,560.00	2,070.00	1,490.00	41.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,766.84	5,757.96	4,008.88	41.05
Approved Total (Overridden) (S\$)		4,600.00		
Nett Amount (S\$)	9,766.84	4,600.00	5,166.84	52.90
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,107.45		

INSPECTION

Date of Assignment:	18/11/2022		
Date Inspected:	21/11/2022	Inspected At:	S3 AUTO WORKSHOP (HQ) 2 Kaki Bukit Ave 2, Autohub #01-14 Singapore 417921
Estimated Period of Repair:	5.0 days		

Adjuster: XING GUO QIANG**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Mar 2023)
Parts:	144	HONDA FIT 1.3 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJD8362M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Buckled	873.60 FL	*873.60 FL
2	1		*TAILGATE WINDSCREEN GLASS RUBBER MOULDING	Necessary	126.50 FL	*126.50 FL
3	1		*TAILGATE FIT EMBLEM	Necessary	28.10 FL	*28.10 FL
4	1		*TAILGATE CENTRE EMBLEM	Not Necessary	32.00 FL	*- FL
5	1		*TAILGATE OUTER GARNISH	Not Necessary	141.90 FL	*- FL
6	1		*TAILGATE LOCK	Cut	235.60 FL	*235.60 FL
7	1		*TAILGATE LOCK CATCH	Not Necessary	29.00 FL	*- FL
8	1		*TAILGATE WEATHERSTRIP	Twisted	153.70 FL	*153.70 FL
9	1		*TAILGATE INNER TRIM BOARD	Broken	287.40 FL	*287.40 FL
10	1		*REAR BUMPER	Deformed	512.30 FL	*512.30 FL
11	1		*REAR BUMPER RH SIDE RETAINER	Cut	23.10 FL	*23.10 FL
12	1		*REAR BUMPER LH SIDE RETAINER	Not Necessary	23.10 FL	*- FL
13	1		*REAR BUMPER TOWING COVER	Cut	18.00 FL	*18.00 FL
14	1		*REAR BUMPER RH SPLASH SHIELD	Torn	55.60 FL	*55.60 FL
15	1		*REAR BUMPER LH SPLASH SHIELD	Not Necessary	55.60 FL	*- FL
16	1		*RH TAILLAMP ASSY	Cracked	387.60 FL	*387.60 FL
17	1		*RH TAILLAMP SPONGE GASKET	Necessary	21.00 FL	*21.00 FL
18	1		*RH TAILLAMP PANEL	Not Necessary	147.00 FL	*- FL
19	1		*SET RH TAILLAMP LOCK CLIPS	Not Necessary	18.00 FL	*- FL
20	1		*LH TAILLAMP ASSY	Cracked	387.60 FL	*387.60 FL
21	1		*LH TAILLAMP SPONGE GASKET	Necessary	21.00 FL	*21.00 FL
22	1		*SET LH TAILLAMP LOCK CLIPS	Not Necessary	18.00 FL	*- FL
23	1		*END PANEL	Buckled	412.30 FL	*412.30 FL
24	1		*END PANEL INNER GARNISH	Deformed	79.30 FL	*79.30 FL
25	1		*REAR FENDER RH	Repair	678.30 FL	*- FL
26	1		*REAR FENDER RH GLASS RUBBER SEAL	Not Necessary	32.00 FL	*- FL
27	1		*REAR FENDER RH INNER TRIM BOARD	Broken	213.90 FL	*213.90 FL
28	1		*REAR FENDER LH INNER TRIM BOARD	Not Necessary	213.90 FL	*- FL
29	1		*SPARE TYRE TOP COVER BOARD	Deformed	292.10 FL	*292.10 FL
30	1		*EXHAUST SILENCER	Repair	613.40 FL	*- FL
31	1		*EXHAUST SILENCER GASKET	Not Necessary	45.30 FL	*- FL
32	1		*EXHAUST SILENCER HEAT SHIELD	Not Necessary	101.10 FL	*- FL
33	1		*TAILGATE WINDSCREEN GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
34	1		*TAILGATE WINDSCREEN GLASS INNER SEAL	Necessary	50.00 FS	*30.00 FS
35	1		*SET TAILGATE OUTER GARNISH CLIP	Not Necessary	50.00 FS	*- FS
36	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	60.00 FS	*20.00 FS
37	1		*SET END PANEL INNER GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
38	1		*END PANEL JOINT SEALANT	Necessary	70.00 FS	*30.00 FS
39	1		*SET REAR BUMPER REVERSE SENSOR	Damaged	320.00 FS	*200.00 FS
40	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
41	1		*SET REAR BUMPER RH SPLASH SHIELD CLIPS	Necessary	40.00 FS	*15.00 FS
42	1		*SET REAR BUMPER LH SPLASH SHIELD CLIPS	Not Necessary	40.00 FS	*- FS
43	1		*SET REAR FENDER RH INNER TRIM BOARD CLIPS	Necessary	60.00 FS	*20.00 FS
44	1		*SET REAR FENDER LH INNER TRIM BOARD CLIPS	Not Necessary	60.00 FS	*- FS
45	1		*REAR FENDER RH JOINT SEALANT	Not Necessary	70.00 FS	*- FS
46	1		*REAR FENDER RH GLASS INNER SEAL	Not Necessary	50.00 FS	*- FS

Report was unsubmitted during this print-out.

3/30/23, 10:49 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR FENDER RH GLASS INNER SEAL	Not Necessary	25.00 FS	*- FS
48	1		*RH TAILLAMP PANEL JOINT SEALANT	Not Necessary	30.00 FS	*- FS
49	1		*REAR NUMBER PLATE	Not Necessary	70.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					7,462.30	4,513.70
- List Item Discount on L Items 20.00/20.00% (S\$)					1,255.46	825.74
Total Parts (S\$)					6,206.84	3,687.96
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CUT /WELD ,PANEL BEATING ,STRAIGHTEN AND ALIGNMENT AFFECTED PARTS AND AREAS .TO REMOVE ,REPLACE AND CHECK ITEMS	New	1,300.00	800.00
2	PUTTY ,SAND DOWN AND RE-SPRAY AFFECTED AREAS AND PARTS ON THE AFFECTED AREAS	New	1,200.00	800.00
3	CHECK AND TEST WIRING SYSTEM AND LIGHTING SYSTEM	New	70.00	30.00
4	APPLY ANTI-RUST COATING ON REPLACED AND REPAIRED PARTS AND AREAS	New	80.00	60.00
5	REMOVE AND REINSTALL TAILGATE WINDSCREEN GLASS AND SEALANTS TO ASSIST REPAIR	New	200.00	120.00
6	REMOVE AND REINSTALL TAILGATE INNER MECHANISM TO NEW TAILGATE	New	120.00	60.00
7	REMOVE AND REPLACE TAILGATE REVERSE CAMERA TO ASSIST REPAIR	New	80.00	40.00
8	REMOVE AND REPLACE REAR INNER TRIMS ,GARNISH AND BOARDS TO ASSIST REPAIR	New	250.00	60.00
9	REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS TO ASSIST REPAIR	New	80.00	40.00
10	REMOVE AND REPLACE EXHAUST SILENCER AND GASKET TO ASSIST REPAIR	New	180.00	60.00
Gross Labour Cost (S\$)			3,560.00	2,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >