

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22011620/RNP3Q2**Date:** 02/05/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNW00008372201		
Claimant Vehicle No :	SMV1301E	Insured Vehicle No :	SMA9336M		
Date of Loss:	13/11/2022	Nature of Claim:	TP	Claim No:	SNM22D208228/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMV1301E	Engine No:	HR12364623C
Make & Model:	NISSAN KICKS PREMIUM, 1.2 L E-POWER (A)	Chassis No:	MNTFEAP15Z0001570
Reg. Date:	17/09/2020 (Man. Year: 2020)	Odometer:	32586 km
Colour:	Orange		
Engine Capacity:	1198 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R17	Rear Tyre Size:	205/55 R17
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,839.00	6,721.20	8,117.80	54.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,176.00	6,041.00	1,135.00	15.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	22,015.00	12,762.20	9,252.80	42.03
+ GST 8.00/8.00% (S\$)	1,761.20	1,020.98	740.22	42.03
Nett Amount (S\$)	23,776.20	13,783.18	9,993.02	42.03

INSPECTION

Date of Assignment:	21/11/2022		
Date Inspected:	22/11/2022	Inspected At:	Tan Chong Motor Sales (HQ) 913 Bukit Timah Road Singapore 589622
Estimated Period of Repair:	11.0 days		

Adjuster: MOHD RASUL**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 13 Apr 2023)	
Parts:	N/A	NISSAN KICKS PREMIUM 1.2 L E-POWER (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMV1301E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	20		*CLIP FR/RR	Necessary	28.00 FN	*28.00 FN
2	1		*EMBLEM -SIDE FR	Necessary	101.90 FN	*101.90 FN
3	1		*EMBLEM -RADIATOR	Not Necessary	556.20 FN	*- FN
4	1		*GRILLE A FRT	Cracked	658.40 FN	*658.40 FN
5	1		*BUMPER ENERG LH	Not Necessary	83.30 FN	*- FN
6	1		*ABS ENERGY FRT	Cracked	53.40 FN	*53.40 FN
7	1		*MOULDING -FR ,LH	Not Necessary	190.00 FN	*- FN
8	1		*MLDG-FR BMPR	Cut	222.10 FN	*222.10 FN
9	1		*MLDG-FR BMPR	Cut	162.30 FN	*162.30 FN
10	1		*FACE -FR BUMPER	Deformed	1,899.10 FN	*1,899.10 FN
11	1		*LAMP ASSY -LH	Not Necessary	1,699.90 FN	*- FN
12	1		*LAMP ASSY -RH	Cracked	1,699.90 FN	*1,699.90 FN
13	1		*BRACKET -BUMP RR	Not Necessary	70.20 FN	*- FN
14	1		*BRACKET -BUMPER	Not Necessary	70.20 FN	*- FN
15	1		*CARPET -LUGGAGE	Not Necessary	314.50 FN	*- FN
16	1		*WEATHER STRIP	Not Necessary	73.80 FN	*- FN
17	1		*A FIN BACK DOOR	Not Necessary	422.40 FN	*- FN
18	1		*RR BUMPER	Deformed	575.70 FN	*575.70 FN
19	1		*BOX -LUGGAGE	Not Necessary	261.20 FN	*- FN
20	1		*PLATE LUGG	Not Necessary	88.00 FN	*- FN
21	4		*CROMMET	Necessary	11.60 FN	*11.60 FN
22	2		*CLIP	Necessary	30.00 FN	*30.00 FN
23	1		*RR PANEL A	Bent	396.60 FN	*396.60 FN
24	1		*DOOR BACK	Bent	835.20 FN	*835.20 FN
25	1		*FINISH ASSY	Not Necessary	356.30 FN	*- FN
26	1		*EMBLEM -BACK DOO	Necessary	127.10 FN	*127.10 FN
27	1		*ORNAMENT -BACK D	Necessary	70.00 FN	*70.00 FN
28	1		*EMBLEM -BACK DOO	Necessary	70.00 FN	*70.00 FN
29	1		*RUBBER -DUM	Necessary	68.90 FN	*68.90 FN
30	1		*GLASS BACK DOOR WDW	Necessary	546.50 FN	*546.50 FN
31	1		*REAR W/SCREEN SEALANT	Necessary	80.00 FS	*80.00 FS
32	1		*SUNDRIES	Necessary	30.00 FS	*20.00 FS
33	1		*FRT LICENCE PLATE	Not Necessary	60.00 FS	*- FS
34	1		*REAR LICENCE PLATE	Not Necessary	60.00 FS	*- FS
35	4		*COVER	Not Necessary	125.20 FS	*- FS
36	2		*COVER	Not Necessary	62.60 FS	*- FS
37	2		*COVER	Not Necessary	33.60 FS	*- FS
38	1		*BRACKET -DIETANC	Not Necessary	536.40 FS	*- FS
39	1		*SENSOR ASSY	Not Necessary	1,878.00 FS	*- FS
40	4		*SENSOR ASSY	Not Necessary	1,001.60 FS	*- FS
41	4		*SENSOR ASSY	Not Necessary	1,001.60 FS	*- FS
42	1		*STAY RH	Bent	209.40 FN	*209.40 FN
43	1		*REINFORCEMENT FR	Bent	510.40 FN	*510.40 FN

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	17,331.50	8,376.50
- Nett Item Discount on N Items 20.00/20.00% (\$\$)	2,492.50	1,655.30

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	14,839.00
						6,721.20
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CONDUCT CONSULT ,RESET & PROGRAMMING	New	240.00	240.00
2	FOCUS & ADJUST H/LAMP ,RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	New	48.00	48.00
3	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS (NPA)	New	0.00	0.00
4	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL FR-2/RR-1	New	360.00	120.00
5	REPLACE REVERSE SENSOR ,NECESSARY ADJUSTMENT & FUNCTION TEST	New	110.00	110.00
6	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY 2X AEA PANEL	New	200.00	200.00
7	INSTALL ULTRAMAX SOLAR FILM -REAR W/SCREEN	New	150.00	150.00
8	RENEW RR WINDSCREEN	New	250.00	250.00
9	REPLACE FR TURNING SENSOR ,NECESSARY ADJUSTMENT & FUNCTION TEST	New	110.00	110.00
10	REPAIR FR UPP PANEL ,HOOD,RH/LH FR FENDER RENEW FR BUMPER	New	980.00	840.00
11	S/PAINT FR BUMPER ,HOOD ,FR PANEL ,RH LH FR FENDER & RH FR DOOR	New	1,500.00	1,375.00
12	REPAIR RH/LH RR FENDER ,RR FLOOR PANEL & RENEW RR BUMPER BACKDOOR& RR END PANEL	New	1,120.00	980.00
13	S/PAINT RR BUMPER ,RR END PANEL ,RR FLOOR PANEL,BACKDOOR ,RH/LH RR FENDER	New	1,500.00	1,250.00
14	CHECK RR LIGHTING	New	48.00	48.00
15	TRANSFER MECHANISM PART FOR BACKDOOR	New	80.00	80.00
16	DISCONNECT /CONNECT MAIN POWER SUPPLY	New	240.00	0.00
17	REMOVE INSTALL SEAT	New	240.00	240.00
Gross Labour Cost (\$\$)			7,176.00	6,041.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >