

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/ZHR/0329/2022
DATE : 16-NOV-2022

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
S(079909)
TEL : 63896111
FAX : 62247175

OWNER'S NAME : MR YONG KOON BEN
ADDRESS : BLK 91 TANGLIN HALT ROAD
#24-314
S(142091)
TELEPHONE NO : 91125412

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TPSMA9336M
VEHICLE NO : SMV1301E
MODEL CODE : FDWARV9P15HDA-D---
MODEL/YEAR : KICKS 1.2L E-POWER PREMIUM PLUS
ENGINE NO : HR12364623C
CHASSIS NO : MNTFEAP15Z0001570
MILEAGE : 1 KM
DATE IN : 16/11/2022
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MUHAMMAD ZUHRI
ACCIDENT DATE : 13/11/2022

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMV1301E

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 CRP	CONDUCT CONSULT, RESET & PROGRAMMING	240.00	/
2 FHI	FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	48.00	/
3 NPI	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS		
4 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL FR-2/RR-1	360.00	120
5 RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	110.00	/
6 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY 2X AEA PANEL	200.00	1000 200
7 SRW	INSTALL ULTRAMAX SOLAR FILM - REAR W/SCREEN	150.00	invoice
8 ZZ/001	RENEW RR WINDSCREEN	250.00	photo
9 ZZ/002	REPLACE FR TURNING SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	110.00	/
10 ZZ/003	REPAIR FR UPP PANEL, HOOD, RH/LH FR FENDER RENEW FR BUMPER	980.00	840
11 ZZ/004	S/PAINT FR BUMPER, HOOD, FR PANEL, RH/LH FR FENDER & RH FR DOOR	1500.00	1375
12 ZZ/005	REPAIR RH/LH RR FENDER, RR FLOOR PANEL & RENEW RR BUMPER, BACKDOOR & RR END PANEL	1120.00	560 980
13 ZZ/006	S/PAINT RR BUMPER, RR END PANEL, RR FLOOR PANEL, BACKDOOR, RH/LH RR FENDER	1500.00	560 560 1250
14 ZZ/007	CHECK RR LIGHTING	48.00	/
15 ZZ/008	TRANSFER MECHANISM PART FOR BACKDOOR	80.00	/
16 ZZ/009	DISCONNECT/CONNECT MAIN POWER SUPPLY	240.00	? X 11

TOTAL LABOUR CHARGES

6936.00

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMV1301E

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
1 CLIP FR/RR(\$1.4X20) <i>ne /</i>	01553-05933	28.00 ✓		
2 EMBLEM-SIDE FR <i>ne /</i>	63890-5RY0A	101.90 ✓		
3 EMBLEM-RADIATOR <i>? Xan</i>	62890-7FW0A	556.20		
4 GRILLE A FRT <i>cm /</i>	62310-5RY5A	658.40 ✓		
5 BUMPER ENERG LW <i>? Xan</i>	62091-5RY0A	83.30		
6 ABS ENERGY FRT <i>? cm /</i>	62090-5RY0A	53.40 ✓		
7 MOULDING-FR, LH <i>? Xan</i>	62087-5RY0A	190.00		
8 MLDG-FR BMR <i>cm /</i>	62086-5RY0A	222.10 ✓		
9 MLDG-FR BMR <i>cm /</i>	62084-5RY0A	162.30 ✓		
10 FACE-FR BUMPER <i>de /</i>	62022-5RY6A	1899.10 ✓		
11 COVER(\$31.3X4) <i>? Xan</i>	28533-6CA0C			125.20
12 COVER(\$31.3X2) <i>? Xan</i>	28533-5RY0B			62.60
13 COVER(\$16.8X2) <i>? Xan</i>	28533-5RY0A			33.60
14 LAMP ASSY-LH <i>? Xan</i>	26060-5RY1B	1699.90		
15 LAMP ASSY-RH <i>cm /</i>	26010-5RY1B	1699.90 ✓		
16 BRACKET-DISTANC <i>? Xan</i>	28452-5RY0B			536.40
17 SENSOR ASSY <i>? Xan</i>	28438-5HK6A			1878.00
18 SENSOR ASSY(\$250.4X4) <i>? Xan</i>	28438-4CLOB			1001.60
19 SENSOR ASSY(\$250.4X4) <i>? Xan</i>	28438-4CC5B			1001.60
20 BRACKET-BUMP RR <i>? Xan</i>	85221-5RF0A	70.20		
21 BRACKET-BUMPER <i>? Xan</i>	85220-5RF0A	70.20		
22 CARPET-LUGGAGE <i>X Xan</i>	84904-5RY0A	314.50		
23 WEATHER STRIP <i>X Xan</i>	90830-5RY0A	73.80		
24 A FIN BACK DOOR <i>X An</i>	90810-5RF3B	422.40		
25 RR BUMPER <i>de /</i>	85022-5RJ0H	575.70 ✓		

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMV1301E

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
26 BOX-LUGGAGE <i>X nn</i>	84975-5RY0A	261.20		
27 PLATE LUGG <i>? X nn</i>	84992-5RY0A	88.00		
28 CROMMET(\$2.9X4) <i>ne</i>	63846-5V000	11.60		
29 CLIP(\$15X2) <i>ne</i>	01553-1HA0A	30.00		
30 RR PANEL A <i>? bt</i>	G9100-5RYAA	396.60		
31 DOOR BACK <i>bt</i>	K010M-5RYMA	835.20		
32 FINISH ASSY <i>? X nn</i>	90900-5RY0A	356.30		
33 EMBLEM-BACK DOO <i>ne</i>	90893-5RY0A	127.10		
34 ORNAMENT-BACK D <i>ne</i>	90892-5RB0A	70.00		
35 EMBLEM-BACK DOO <i>ne</i>	90890-5RB0A	70.00		
36 RUBBER-DUM <i>ne</i>	G2G16-89900	68.90		
37 REAR W/SCREEN SEALANT <i>ne</i>	SEALANT - 4			80.00
38 GLASS BACK DOOR WDW <i>ne / pleks</i>	90300-5RJ0A	546.50		
39 SUNDRIES	NPN		<i>no</i>	30.00
40 FRT LICENCE PLATE <i>X nn</i>	FLP			60.00
41 REAR LICENCE PLATE <i>Se X nn</i>	RLP			60.00

SUB TOTAL

LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)

GRAND TOTAL

OVERALL TOTAL

8276.50	11742.70	0.00	4859.00	100
	2348.54	0.00	0.00	
6621.20	9394.16	0.00	4859.00	100
	14263.16			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SMV1301E

TOTAL LABOUR CHARGES	5936.00
TOTAL SPARE PARTS CHARGES	14263.16
GRAND TOTAL	21199.16 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME

SURVEYED DATE

AUTHORIZED DATE

EXCESS CLAUSE

LIABILITY

REMARKS

Rasul - Hp 90010068

22/11/22 @ 1500

10 days

0.00

0.00

Rasul before paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: