2/6/23, 9:06 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22011630/SVP3E2

06/02/2023 Date:

REFERENCE

Date of Loss:

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

DMPCSNW00198852208

Odometer:

Claimant Vehicle

FBT9810R

Insured Vehicle No:

Policy No:

SKH678Y

No:

05/11/2022

Nature of Claim: TP

Claim No:

11729 km

SNM22D208285/C02/LEWLC

Yes

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBT9810R**

Make & Model: YAMAHA NMAX155, 155cc Reg. Date:

12/07/2022 (Man. Year: 2022)

Engine No: G3L8E0971115 Chassis No: MH3SG5680NK126191

Colour: Silver

Engine Capacity:

155 cc

Market Value/New Car Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): **Engine Modification:** No Yes

CONDITION OF TYRES

Front Tyre Size: 110/70-13 Rear Tyre Size: 140/70-13 Front Left Side: Rear Left Side: Maxxis 5 mm Maxxis 5 mm Front Right Side: Rear Right Side: 0 mm 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		3,085.00	141.00	2,944.00	95.43
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,300.00	340.00	960.00	73.85
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	4,385.00	481.00	3,904.00	89.03
	Approved Total (Overridden) (S\$)		400.00		
	(S\$)	4,385.00	400.00	3,985.00	90.88
	+ GST 7.00/7.00% (S\$)	306.95	28.00	278.95	90.88
	Nett Amount (S\$)	4,691.95	428.00	4,263.95	90.88

INSPECTION

Date of Assignment: 21/11/2022

EQBH PTE LTD (HQ)

Date Inspected: 18/11/2022 Inspected At: 25 Kaki Bukit Road 4, #03-79

Singapore 417800

Estimated Period of Repair: 2.0 days

S Mohamed Irfan Bin Mohamed Igubal Manager: **VERON CHEN** Adjuster:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 06 Feb 2023)

Parts: N/A YAMAHA NMAX155 155cc (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBT9810R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*YAMAHA FRONT SUSPENSION	Repair	600.00 F	*- FL
2	1		*YAMAHA TRIPLE CLAMP (BOTTOM)	Not Necessary	200.00 F	*- FL
3	1		*YAMAHA STEERING CONE	Not Necessary	110.00 F	*- FL
4	1		*YAMAHA FRONT RIM	Not Necessary	360.00 F	*- FL
5	1		*YAMAHA FRONT WHEEL SHAFT	Not Necessary	45.00 F	*- FL
6	2		*YAMAHA FRONT WHEEL BEARING	Not Necessary	70.00 F	*- FL
7	2		*YAMAHA FRONT WHEEL SEAL	Not Necessary	30.00 F	*- FL
8	2		*YAMAHA FRONT WHEEL BUSH	Not Necessary	60.00 F	*- FL
9	1		*YAMAHA FRONT WHEEL SHAFT CENTER BUSH	Not Necessary	20.00 F	*- FL
10	1		*YAMAHA REAR BRAKE LEVER (LEFT)	Not Necessary	35.00 F	*- FL
11	1		*YAMAHA REAR BRAKE LEVER HOLDER (LEFT)	Not Necessary	45.00 F	*- FL
12	1		*YAMAHA REAR BRAKE LEVER CABLE (LEFT)	Not Necessary	45.00 F	*- FL
13	1		*YAMAHA FRONT BRAKE CALIPER	Not Necessary	180.00 F	*- FL
14	1		*YAMAHA FRONT BRAKE PAD	Not Necessary	35.00 F	*- FL
15	1		*YAMAHA FRONT BRAKE DISC	Not Necessary	110.00 F	*- FL
16	1		*YAMAHA FRONT SIGNAL LIGHT	Not Necessary	60.00 F	*- FL
17	1		*YAMAHA FRONT MUDGUARD (SILVER)	Scratched	75.00 F	*75.00 FL
18	1		*YAMAHA FRONT MUDGUARD HOLDER (MATTE BLACK)	Not Necessary	55.00 F	*- FL
19	2		*YAMAHA FLOORBOARD (MATTE BLACK)	Not Necessary	120.00 F	*- FL
20	1		*YAMAHA FLOORBOARD COVER (SILVER)	Not Necessary	65.00 F	*- FL
21	1		*YAMAHA SIDE FAIRING 1	Not Necessary	55.00 F	*- FL
22	1		*YAMAHA SIDE FAIRING 2	Not Necessary	60.00 F	*- FL
23	1		*YAMAHA TAIL FAIRING (SILVER)	Scratched	65.00 F	*65.00 FL
24	1		*YAMAHA HEADLIGHT	Not Necessary	380.00 F	*- FL
25	1		*YAMAHA HANDLE BAR	Not Necessary	95.00 F	*- FL
26	1		*YAMAHA FRONT WINDSHIELD	Not Necessary	45.00 F	*- FL
27	1		*MOTUL BRAKE FLUID	Not Necessary	15.00 F	*- FL
28	1		*FRONT NUMBER PLATE	Dented	15.00 FS	*15.00 FS
29	1		*PLAYLIFT GRIP	Not Necessary	35.00 F	*- FL
F=Fra	anchise	part. S=Spcl	Nett. L=ListItemDisc.	,		
				Sub Total (S\$)	3,085.00	155.00
	- List Item Discount on L Items 0.00/10.00% (S\$)				0.00	14.00
				Total Parts (S\$)	3,085.00	141.00
				,		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	ALIGNMENT (CHASSIS)	New	580.00	0.00
2	TOWING 1-TRIP (REPORTING CENTER TO WORKSHOP) }	New	80.00	60.00
3	TOWING 1-TRIP (WORKSHOP TO REPORTING CENTER) }	New	80.00	0.00
4	TOWING 1-TRIP (TP TO WORKSHOP)	New	80.00	0.00
5	LABOR	New	480.00	280.00
		Gross Labour Cost (S\$)	1,300.00	340.00

< END OF ESTIMATES >

Report was unsubmitted during this print-out.