



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKV 2795E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BOOT COVER (N)	DENTED	984.00	984.00
1	REAR BOOT LOGO (N)	NOT NECESSARY	101.00	-
1	REAR BOOT OUTLANDER PLATE (N)	NECESSARY	121.00	121.00
1	REAR BOOT MIVEC PLATE (N)	NECESSARY	91.00	91.00
1	REAR BUMPER (N)	DEFORMED	807.00	807.00
2	REAR BUMPER SIDE RETAINER @\$78.00 (N)	NOT NECESSARY	156.00	-
1	REAR BUMPER SPOILER (N)	DEFORMED	489.00	489.00
	LESS 10% DISCOUNT		-274.90	-249.20
			2,474.10	2,242.80
<u>SPECIAL NETT ITEMS</u>				
1	REVERSE SENSOR (SN)	DAMAGED	428.00	200.00
1	REAR WINDSCREEN GLASS SEAL (SN)	NECESSARY	98.00	40.00
1	WINDSCREEN GLASS SEALANT (SN)	NECESSARY	80.00	40.00
			606.00	280.00
<u>LABOUR</u>				
	TO DISMANTLE & REPLACE DAMAGE PARTS, PANEL BEAT WHERE NECESSARY.		780.00	500.00
	TO PUTTY, APPLY PRIMER & SPRAY PAINT ON THE AFFECTE PORTION.		780.00	400.00
	TO DISMANTLE & REFIX REAR WINDSCREEN GLASS.		180.00	120.00
	TO CHECK WIRING FUNCTIONS.		120.00	30.00
			1,860.00	1,050.00
GRAND TOTAL			4,940.10	3,572.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,800.00

Report Ref No. CS/SMR22011632/Aqy3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.