

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	LONPAC INSURAN		Ref:	CS3/LPC22011636/Sqy3e2	
	300 BEACH ROAD SINGAPORE 1995		Date:	28/12/2022	
				Code:	LPC2
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	GBF 9616J	Veh. Inspected		GBC 2727J
	Policy No.	Policy No. Coverage (\$)			0.00
	Claim No.	22/22/22/VC05/02601	Excess (\$)		0.00
	Assign From	GERALD POH	Assign Date		18/11/2022
2.	Vehicle Particulars & Condition				
	Make & Model	TOYOTA HIACE	c.c		2982
	Engine No.	HIDDEN	Year of Reg.		2011
	Chassis No.	JTFHT02P300081829	Colour		WHITE
	Odometer	422368 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM
	General	FAIR			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	195 R15	HABILEAD		6 mm
	L/H Front Tyre	195 R15	HABILEAD		6 mm
	R/H Rear Tyre	195 R15	HABILEAD		6 mm
	L/H Rear Tyre	195 R15	HABILEAD		6 mm
4. Description of Damages					
		THE VEHICLE SUSTAINED DAMAGES AT THE FRONT, REAR PORTION, N/S AND O/S BODY.			
5.	General Information				
	Accident Date	17/11/2022	Inspect Date /	Time	18/11/2022 ( 04:30 PM )
	Survey held at	ECO AUTOMOBILE CLAIMS & REPAIR PTE LTD			
		15 KAKI BUKIT ROAD 4 #01-53 BARTLEY BIZ CENTRE SINGAPORE 417808			
5a.	a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/LPC22011636/Sqy3e2

Inspected By

S MOHAMED IRFAN BIN MOHAMED IQUBAL

K.K.LAU CPT(RET)

Asst. Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser