

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22011638/TNP3E2**Date:** 10/01/2023REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00098532200

**Claimant Vehicle
No :** SKZ8652Z**Insured Vehicle
No :** SJL1996M

Date of Loss: 14/11/2022

Nature of Claim: TP

Claim
No: SNM22D208224/C03/LEWLCDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKZ8652Z**

Make & Model: MERCEDES-BENZ C180K, 1.8 (A)

Engine No: 27195230987971

Reg. Date: 29/02/2008 (Man. Year: 2007)

Chassis No: WDD2040462A087779

Colour: Red

Odometer: 124860 km

Engine Capacity: 1796 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size: 225/45 R17

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,868.50	3,039.60	16,828.90	84.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,710.00	860.00	2,850.00	76.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,578.50	3,899.60	19,678.90	83.46
Approved Total (Overridden) (S\$)		3,100.00		
(S\$)	23,578.50	3,100.00	20,478.50	86.85
+ GST 8.00/8.00% (S\$)	1,886.28	248.00	1,638.28	86.85
Nett Amount (S\$)	25,464.78	3,348.00	22,116.78	86.85

INSPECTION

Date of Assignment: 18/11/2022

Date Inspected: 21/11/2022 Inspected At:

Bifrost Auto Pte Ltd (Kaki Bukit)
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Jan 2023)
Parts:	143	MERCEDES-BENZ C180K 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKZ8652Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,496.00 FL	*1,496.00 FL
2	1		*FRONT BUMPER RH CHROME MOULDING	Not Necessary	156.00 FL	*- FL
3	1		*FRONT BUMPER LH CHROME MOULDING	Not Necessary	156.00 FL	*- FL
4	1		*FRONT BUMPER LH FOG LAMP	Not Necessary	498.00 FL	*- FL
5	1		*FRONT BUMPER LH FOG LAMP COVER	Not Necessary	84.00 FL	*- FL
6	1		*FRONT BUMPER LH FOG LAMP COVER CHROME	Not Necessary	101.00 FL	*- FL
7	1		*FRONT BUMPER LH SIDE RETAINER	Not Necessary	43.00 FL	*- FL
8	1		*FRONT BUMPER RH SIDE RETAINER	Not Necessary	43.00 FL	*- FL
9	1		*LH HEADLAMP ASSY	Not Necessary	2,020.00 FL	*- FL
10	1		*LH FRONT FENDER	Bent	891.00 FL	*891.00 FL
11	1		*LH FRONT FENDER EMBLEM	Necessary	72.00 FL	*72.00 FL
12	1		*LH FRONT FENDER SPLASH SHIELD (FRONT)	Not Necessary	188.00 FL	*- FL
13	1		*LH FRONT FENDER SPLASH SHIELD (REAR)	Not Necessary	156.00 FL	*- FL
14	1		*LH FRONT SHOCK ABSORBER	Not Necessary	732.00 FL	*- FL
15	1		*LH FRONT LOWER ARM	Not Necessary	641.00 FL	*- FL
16	1		*LH FRONT KNUCKLE ARM	Not Necessary	1,140.00 FL	*- FL
17	1		*LH FRONT WHEEL BEARING	Not Necessary	485.00 FL	*- FL
18	1		*LH FRONT WHEEL HUB	Not Necessary	381.00 FL	*- FL
19	1		*LH FRONT UPPER ARM	Not Necessary	742.00 FL	*- FL
20	1		*LH FRONT TIE ROD END	Not Necessary	156.00 FL	*- FL
21	1		*STEERING RACK AND PINION	Not Necessary	2,745.00 FL	*- FL
22	1		*LH SIDE MIRROR ASSY	Not Necessary	1,353.00 FL	*- FL
23	1		*LH SIDE MIRROR ASSY COVER	Not Necessary	236.00 FL	*- FL
24	1		*LH FRONT DOOR	Not Necessary	2,578.00 FL	*- FL
25	1		*LH FRONT DOOR UPPER CHROME MOULDING	Not Necessary	165.00 FL	*- FL
26	1		*LH FRONT DOOR WEATHERSTRIP	Not Necessary	285.00 FL	*- FL
27	1		*LH FRONT DOOR LOCK	Not Necessary	405.00 FL	*- FL
28	1		*LH FRONT DOOR INNER TRIM BOARD	Not Necessary	1,231.00 FL	*- FL
29	1		*LH FRONT DOOR LOWER RUBBER SEAL	Not Necessary	62.00 FL	*- FL
30	1		*LH FRONT DOOR FRAME BLACK GARNISH	Not Necessary	77.00 FL	*- FL
31	1		*LH FRONT DOOR FRAME SIDE BLACK GARNISH	Not Necessary	54.00 FL	*- FL
32	1		*LH SIDE ROCKER PANEL SPOILER	Not Necessary	708.00 FL	*- FL
33	1		*FRONT LH SPORT RIM (ORIGINAL)	Cut	885.00 FL	*885.00 FL
34	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
35	1		*FRONT LH TYRE	Not Necessary	650.00 FS	*- FS
36	1		*BRAKE FLUID	Not Necessary	80.00 FS	*- FS
37	1		*LH FRONT FENDER SPLASH SHIELD CLIPS (FRONT)	Not Necessary	60.00 FS	*- FS
38	1		*LH FRONT FENDER SPLASH SHIELD CLIPS (REAR)	Not Necessary	60.00 FS	*- FS
39	1		*LH FRONT DOOR INNER TRIM BOARD CLIPS	Not Necessary	70.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **21,965.00** **3,374.00**
- List Item Discount on L Items 10.00/10.00% (\$\$) 2,096.50 334.40

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (\$)	19,868.50
						3,039.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE, CHECK, REPLACE AND REINSTALL DAMAGES BODYPARTS. TO PANEL BEATING, CUT / WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	1,200.00	300.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,000.00	450.00
3	CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS	New	80.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	60.00	30.00
5	REFOCUS AND ADJUST HEADLAMPS ASSY	New	80.00	0.00
6	TEST DRIVE AND ADJUST WHEEL ALIGNMENT SYSTEM	New	180.00	80.00
7	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS TO ASSIST REPAIR	New	480.00	0.00
8	REMOVE AND REPLACE LH FRONT DOOR INNER MECHANISM TO NEW DOOR	New	180.00	0.00
9	RESET AND DIAGNOSE FAULT CODE AND CONTROL UNIT AFTER REPAIR	New	450.00	0.00
Gross Labour Cost (\$\$)			3,710.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >